

ID No. 884	<b>Product/Process Change Notification</b>	Date 19.04.2022
<b>Product</b>	<b>Ordering Code</b>	
PLS83-W REL.1.1 CI	L30960-N6535-A101	
Ordering Code changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Product	New Ordering Code	

**Reason of Change:**

- |   |  |
|---|--|
| <input checked="" type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement             | <input type="checkbox"/> Location of production moved                    |
| <input type="checkbox"/> Quality improvement              | <input type="checkbox"/> Other:  |

Description of change:	Thales is going to introduce a new firmware to improve the stability of PPP connection over MUX. This change is not approval relevant.  SW revision is <ul style="list-style-type: none"> <li>- 01.006 for ROW image</li> <li>- 01.006 for AT&amp;T image</li> <li>- 01.005T for VzW image</li> </ul>
Availability of SW :	CW15/2022
Availability of modules ex warehouse:	June/2022
<b>Timing note:</b>	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES assumes that the customer agrees to the change.
<b>Quality assurance measurements:</b>	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.

**Attachments: no**

2022/4/29

29.04.2022

**X** WANG JIANFENG

**X**

Product Program Manager  
Signed by: WANG Jianfeng

Vice President Quality Management  
Signed by: ERDMANN Joerg