

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	042	0000000585	See list below	Circuit Protection	CSO Clip	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)



List of part numbers affected			
0751.0500	0751.0501	0751.0502	0751.0503
0751.0505	0751.0506	0751.0507	0751.0508
3-111-506	3-111-507	3-124-244	3-124-245

2 Type of change

- Change of material

3 Detailed description of change

The material of the CSO series fuse clip changes to a different copper alloy. Fuse clips manufactured with the new material can be identified by a mark "B1" or "B2" on the clip. This change has no effect on the rating and the approval of the fuse clip.

Old material	New material
Copper alloy	Different copper alloy, which may lead to a higher clip temperature by approximately 15K.
Old product appearance	New product appearance
	

4 Reason of change

There is a shortage of the old raw material due to force majeure.

5 Release date

The change takes effect in week 08/2022 (Date code 2208 or higher on label).

6 Impact of change and recommended action

Form	Yes	No action required
Fit	No	-
Function	Yes	Please consider the impact of higher worst-case clip temperature in your application
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	CSO Clip

Product Change Notification					PCN CSO material change		
owner	creation date	release date	released by	change order no	rev	page	D10-061-218
kesslema	19.11.2021	19.11.2021	schulejo	2022915	B	1 of 1	