

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	063	0000000598	0031.1667	Circuit protection	FEU fingergrip carrier 6.3x32	n/a
			0000000685	0031.1812		FEU (Grip) carrier 6.3x32	
		003	0000000523	0031.1761		FEU with fingergrip 6.3x32	
			0031.1765	FEU with fingergrip 6.3x32			
			0031.1755	FEU with fingergrip 6.3x32			
			0000000679	0031.1804		FEU (Grip) with fuse carrier 6.3x32	


\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

**2 Type of change**

- Improved electrical contact

**3 Detailed description of change**

The contact spring on FEU finger grip carrier and FEU (Grip) carrier for 6.3x32mm fuse is improved.



**4 Reason of change**

Product improvement.

**5 Release date**

The change will be rolled-out starting ww 06/2018 (Date code 1806 or higher on label) and lasts approx. 6 months, depending on stock.

**6 Impact of change and recommended action**

Form	Yes	Contact spring of fuse carrier changed
Fit	No	No change for dimension
Function	No	No functional change
Production Site	No	No change of the production site
Product Label	No	No label on the change
Packaging	No	No change in packaging

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">Data sheet</a>	Fusecarrier FEU
<a href="#">Data sheet</a>	Fuseholder FEU grip
<a href="#">Data sheet</a>	Fusecarrier FEU grip

Product Change Notification					FEU fingergrip improvement		
owner	creation date	release date	released by	change order no	rev	page	D10-016-241
dislercy	08.06.2017	21.12.2017	haeckima	2013038	A	1 of 1	