

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|-------|----------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 01 | 001 | 025 | 0000000200 | See list below | Fuses | USI 1206 0.5 – 6.3 A | n/a |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)



List of part numbers affected

| Rated current [A] | Order Number | Rated current [A] | Order Number | Rated current [A] | Order Number |
|-------------------|--------------|-------------------|--------------|-------------------|--------------|
| 0.5 | 3413.0213.11 | 1.3 | 3413.0217.11 | 3.2 | 3413.0221.11 |
| | 3413.0213.22 | | 3413.0217.22 | | 3413.0221.22 |
| | 3413.0213.24 | | 3413.0217.24 | | 3413.0221.24 |
| | 3413.0213.26 | | 3413.0217.26 | | 3413.0221.26 |
| 0.6 | 3413.0214.11 | 1.6 | 3413.0218.11 | 4.0 | 3413.0222.11 |
| | 3413.0214.22 | | 3413.0218.22 | | 3413.0222.22 |
| | 3413.0214.24 | | 3413.0218.24 | | 3413.0222.24 |
| | 3413.0214.26 | | 3413.0218.26 | | 3413.0222.26 |
| 0.8 | 3413.0215.11 | 2.0 | 3413.0219.11 | 5.0 | 3413.0223.11 |
| | 3413.0215.22 | | 3413.0219.22 | | 3413.0223.22 |
| | 3413.0215.24 | | 3413.0219.24 | | 3413.0223.24 |
| | 3413.0215.26 | | 3413.0219.26 | | 3413.0223.26 |
| 1.0 | 3413.0216.11 | 2.5 | 3413.0220.11 | 6.3 | 3413.0224.11 |
| | 3413.0216.22 | | 3413.0220.22 | | 3413.0224.22 |
| | 3413.0216.24 | | 3413.0220.24 | | 3413.0224.24 |
| | 3413.0216.26 | | 3413.0220.26 | | 3413.0224.26 |

2 Type of change

- Change of body material
- Slightly adapted fuse elements
- Modified marking letter font

3 Detailed description of change

| Old product appearance (Example) | New product appearance (Example) |
|---|---|
|  |  |

4 Reason of change

- Change of body material due to material phase out
- Slightly adapted fuse element due to production process improvements
- Modified marking letter font due to production software update

5 Release date

The change will be rolled-out starting ww 50/2016 (Date code 1650 or higher on label) and lasts approx. 6 months depending on the variant.

| Product Change Notification | | | | | PCN USI 1206 | | |
|-----------------------------|---------------|--------------|-------------|-----------------|--------------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-009-665 |
| ganderka | 2016-10-10 | 2017-01-05 | nowakfr | 2011824 | A | 1 of 2 | |

6 Impact of change and recommended action

| | | |
|---------------|-----|--|
| Form | Yes | Change of body materiel / Modified marking letter font |
| Fit | No | No change for dimension |
| Function | No | No change in function |
| Manufacturing | No | No change for manufacturing site |
| Label | No | No change on label |
| Packaging | No | No change in packaging |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|----------------------------|---------------------|
| Data Sheet | Data Sheet USI 1206 |

| | | | | | | | |
|-----------------------------|---------------|--------------|-------------|-----------------|--------------|--------|-------------|
| Product Change Notification | | | | | PCN USI 1206 | | |
| owner | creation date | release date | released by | change order no | rev | page | D10-009-665 |
| ganderka | 2016-10-10 | 2017-01-05 | nowakfr | 2011824 | A | 2 of 2 | |