DIGI

Product Change Notification	Date December 19, 2024

Product	IX10/IX20/IX20W/IX30/IX40

Description of change	New firmware version 24.9.79.161 available for all IX routers. This is a major production release. Digi recommends all customers update their IX products to firmware v24.9.79.161

Reason for Change	New Firmware Version 24.9.79.161 provides: • New Features • Enhancements • Bug Fixes • Security Fixes See Release Notes for more details.

Product Notice	A new stable firmware version has been released for the IX, version 24.9.79.161. Use the link below to view the full list of changes, features, and fixes included in the new firmware. IX Release Notes **To take advantage of the new features, you must take action to update your device.** Refer to the instructions to update your firmware in the release notes above for more information. Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team

Affected SKUs	IX10-00G4, IX10-00N4, IX10-00C6, IX15-00G4-XB2, IX15-00G4-XBP2, IX20-W0P4, IX20-00P4, IX20-W007, IX20-0007, IX20-W0G4, IX20-00G4, IX20-W0N4, IX20-00N4, IX20-0045, IX20-W0M1, IX20-00M1, IX30-00P7, IX30-00G4, IX30-00A4, IX40-04, IX40-05

Timing of Change	Effective Immediately