

| | | |
|------------------------|---|--------------------|
| ID No. 830 | Product/Process Change Notification | Date 30.06.2021 |
| Product | Ordering Code | |
| PLS83-W Rel.1 | L30960-N6530-A100 | |
| PLS63-W Rel.1 | L30960-N6520-A100 | |
| PLS83-EP Rel.1 | L30960-N6570-A100 | |
| PLS63-EP Rel.1 | L30960-N6560-A100 | |
| Ordering Code changes: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| Product | New Ordering Code | |

Reason of Change:

- | | |
|---|--|
| <input checked="" type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

| | |
|--|--|
| Description of change: | With this PCN Thales is going to introduce an improved handling of emergency call (120, 122) in China. This changes doesn't affect the existing certificates. |
| Schedule details: | CW26/2021 |
| Availability of SW for evaluation: | CW26/2021 |
| Availability of modules ex THALES DIS AIS Deutschland warehouse: | CW33/2021 |
| Timing note: | If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change. |

| | |
|--|--|
| Quality assurance measurements: | The new version fulfils all internal test requirements according to our Quality Management process and philosophy. |
|--|--|

Attachments:

2021/7/6

06.07.2021

X WANG JIANFENG

X 

Product Lifecycle Manager
Signed by: WANG Jianfeng

Vice President Quality Management
Signed by: ERDMANN Joerg