

Product Code Change

Issue Date
August 27, 2014

No. PP-L-1408001

Tactile switches


The modifications of manufacturing country and product code change for B3FS series.

[Effective Date]



Effective as of December 01, 2014

[Changes]

Models	Old Product Code	New Product Code
B3FS-1050P	B3FS1032D	B3FS6003H
B3FS-1052P	B3FS1036G	B3FS6004F
B3FS-1012P	B3FS1019G	B3FS1107M
B3FS-1010P	B3FS1018R	B3FS1108H



[Other Changes]

Before the change	After the change
<p>The country of origin. MADE IN JAPAN</p> <p>The display of a packing label on reel. Production factory abbreviation change Lot No □□□□R□</p> <p>Display of the country of origin. MADE IN JAPAN</p>  <p>□□□□R□ MADE IN JAPAN</p>	<p>The country of origin. MADE IN CHINA</p> <p>The display of a packing label on reel. Production factory abbreviation change Lot No □□□□C□</p> <p>Display of the country of origin. MADE IN CHINA</p>  <p>□□□□C□ MADE IN CHINA</p>

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.