



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
LC4-1.950-F7P	C	D
LC4-1.950-F7P-2	C	D
LC4-1.950-F7P-4	C	D
LC4-1.950-F7P-5	C	D
LC4-1.950-F7P-6	C	D
LC4-1.950-F7P-9	C	D
LC4-10.0-F7P	C	D
LC4-10.0-F7P-2	C	D
LC4-10.0-F7P-4	C	D
LC4-10.0-F7P-5	C	D
LC4-10.0-F7P-6	C	D
LC4-10.0-F7P-9	C	D
LC4-2.0-F7P	C	D
LC4-2.0-F7P-2	C	D
LC4-2.0-F7P-4	C	D
LC4-2.0-F7P-5	C	D
LC4-2.0-F7P-6	C	D
LC4-2.0-F7P-9	C	D
LC4-2.375-F7P	C	D
LC4-2.375-F7P-2	C	D
LC4-2.375-F7P-4	C	D
LC4-2.375-F7P-5	C	D
LC4-2.375-F7P-6	C	D
LC4-2.375-F7P-9	C	D
LC4-3.5-F7P	C	D
LC4-3.5-F7P-2	C	D
LC4-3.5-F7P-4	C	D
LC4-3.5-F7P-5	C	D
LC4-3.5-F7P-6	C	D

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
LC4-3.5-F7P-9	C	D
LC4-6.0-F7P	C	D
LC4-6.0-F7P-2	C	D
LC4-6.0-F7P-4	C	D
LC4-6.0-F7P-5	C	D
LC4-6.0-F7P-6	C	D
LC4-6.0-F7P-9	C	D
LC4-8.0-F7P	C	D
LC4-8.0-F7P-2	C	D
LC4-8.0-F7P-4	C	D
LC4-8.0-F7P-5	C	D
LC4-8.0-F7P-6	C	D
LC4-8.0-F7P-9	C	D
FLP25R10.0-SA	G	H
FLP25R13.0-SG	G	H
FLP25R13.0-SR	G	H
FLP25R24.0-SG	G	H
FLP25R24.0-SUG	G	H
FLP25R24.0-UG	G	H
FLP25R3.5-UBW	G	H
FLP25R4.5-SUR	G	H
FLP25R4.5-UR	G	H
FLP25R5.0-SBC	G	H
FLP25R5.0-SUR	G	H
FLP25R6.0-SA	G	H
FLP25R6.0-SUG	G	H
FLP25R6.0-SUR	G	H
FLP25R6.0-UBW	G	H
FLP25R6.0-UW	G	H

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
FLP25R6.5-SA	G	H
FLP25R6.5-SUG	G	H
FLP25R6.5-SUR	G	H
FLP25R6.5-UBW	G	H
FLP25R6.5-UW	G	H
FLP25R60.0-UBW	G	H
FLP25R8.0-SG	G	H
FLP25R9.5-SUG	G	H
FLP25V10.0-BC	G	H
FLP25V10.0-SBC	G	H
FLP25V13.0-SG	G	H
FLP25V13.0-SR	G	H
FLP25V2.0-SA	G	H
FLP25V2.0-SUG	G	H
FLP25V2.0-SUR	G	H
FLP25V2.0-UBW	G	H
FLP25V3.0-SA	G	H
FLP25V3.0-SUG	G	H
FLP25V3.0-SUR	G	H
FLP25V4.0-BC	G	H
FLP25V4.0-SBC	G	H
FLP25V4.0-SG	G	H
FLP25V40.0-UW	G	H
FLP25V6.0-BC	G	H
FLP25V6.0-SA	G	H
FLP25V6.0-SG	G	H
FLP25V6.0-SUG	G	H
FLP25V6.0-SUR	G	H
FLP25V6.0-UBW	G	H

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
FLP25V6.0-UW	G	H
FLP25V8.0-UW	G	H
FLP25V9.0-BC	G	H
FR4-13.0-SG-F7P	A	B
FR4-13.0-SG-F7P-2	A	B
FR4-13.0-SG-F7P-4	A	B
FR4-13.0-SG-F7P-5	A	B
FR4-13.0-SG-F7P-6	A	B
FR4-13.0-SG-F7P-9	A	B
FR4-13.0-SR-F7P	A	B
FR4-13.0-SR-F7P-2	A	B
FR4-13.0-SR-F7P-4	A	B
FR4-13.0-SR-F7P-5	A	B
FR4-13.0-SR-F7P-6	A	B
FR4-13.0-SR-F7P-9	A	B
FR4-3.5-UBW-F7P	A	B
FR4-3.5-UBW-F7P-2	A	B
FR4-3.5-UBW-F7P-4	A	B
FR4-3.5-UBW-F7P-5	A	B
FR4-3.5-UBW-F7P-6	A	B
FR4-3.5-UBW-F7P-9	A	B
FR4-5.0-SUR-F7P	A	B
FR4-5.0-SUR-F7P-2	A	B
FR4-5.0-SUR-F7P-4	A	B
FR4-5.0-SUR-F7P-5	A	B
FR4-5.0-SUR-F7P-6	A	B
FR4-5.0-SUR-F7P-9	A	B
FR4-6.0-SA-F7P	A	B
FR4-6.0-SA-F7P-2	A	B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected		Old Rev.	A	New Rev.	B
	FR4-6.0-SA-F7P-4		A		B
	FR4-6.0-SA-F7P-5		A		B
	FR4-6.0-SA-F7P-6		A		B
	FR4-6.0-SA-F7P-9		A		B
	FR4-6.0-SUG-F7P		A		B
	FR4-6.0-SUG-F7P-2		A		B
	FR4-6.0-SUG-F7P-4		A		B
	FR4-6.0-SUG-F7P-5		A		B
	FR4-6.0-SUG-F7P-6		A		B
	FR4-6.0-SUG-F7P-9		A		B
	FR4-6.0-SUR-F7P		A		B
	FR4-6.0-SUR-F7P-2		A		B
	FR4-6.0-SUR-F7P-4		A		B
	FR4-6.0-SUR-F7P-5		A		B
	FR4-6.0-SUR-F7P-6		A		B
	FR4-6.0-SUR-F7P-9		A		B
	FR4-6.0-UBW-F7P		A		B
	FR4-6.0-UBW-F7P-2		A		B
	FR4-6.0-UBW-F7P-4		A		B
	FR4-6.0-UBW-F7P-5		A		B
	FR4-6.0-UBW-F7P-6		A		B
	FR4-6.0-UBW-F7P-9		A		B
	FR4-6.5-SA-F7P		A		B
	FR4-6.5-SA-F7P-2		A		B
	FR4-6.5-SA-F7P-4		A		B
	FR4-6.5-SA-F7P-5		A		B
	FR4-6.5-SA-F7P-6		A		B
	FR4-6.5-SA-F7P-9		A		B
	FR4-6.5-SUG-F7P		A		B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
FR4-6.5-SUG-F7P-2	A	B
FR4-6.5-SUG-F7P-4	A	B
FR4-6.5-SUG-F7P-5	A	B
FR4-6.5-SUG-F7P-6	A	B
FR4-6.5-SUG-F7P-9	A	B
FR4-6.5-SUR-F7P	A	B
FR4-6.5-SUR-F7P-2	A	B
FR4-6.5-SUR-F7P-4	A	B
FR4-6.5-SUR-F7P-5	A	B
FR4-6.5-SUR-F7P-6	A	B
FR4-6.5-SUR-F7P-9	A	B
FR4-6.5-UBW-F7P	A	B
FR4-6.5-UBW-F7P-2	A	B
FR4-6.5-UBW-F7P-4	A	B
FR4-6.5-UBW-F7P-5	A	B
FR4-6.5-UBW-F7P-6	A	B
FR4-6.5-UBW-F7P-9	A	B
FV4-13.0-SG-F7P	A	B
FV4-13.0-SG-F7P-2	A	B
FV4-13.0-SG-F7P-4	A	B
FV4-13.0-SG-F7P-5	A	B
FV4-13.0-SG-F7P-6	A	B
FV4-13.0-SG-F7P-9	A	B
FV4-13.0-SR-F7P	A	B
FV4-13.0-SR-F7P-2	A	B
FV4-13.0-SR-F7P-4	A	B
FV4-13.0-SR-F7P-5	A	B
FV4-13.0-SR-F7P-6	A	B
FV4-13.0-SR-F7P-9	A	B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
FV4-2.0-UBW-F7P	A	B
FV4-2.0-UBW-F7P-2	A	B
FV4-2.0-UBW-F7P-4	A	B
FV4-2.0-UBW-F7P-5	A	B
FV4-2.0-UBW-F7P-6	A	B
FV4-2.0-UBW-F7P-9	A	B
FV4-4.0-SBC-F7P	A	B
FV4-4.0-SBC-F7P-2	A	B
FV4-4.0-SBC-F7P-4	A	B
FV4-4.0-SBC-F7P-5	A	B
FV4-4.0-SBC-F7P-6	A	B
FV4-4.0-SBC-F7P-9	A	B
FV4-6.0-SA-F7P	A	B
FV4-6.0-SA-F7P-2	A	B
FV4-6.0-SA-F7P-4	A	B
FV4-6.0-SA-F7P-5	A	B
FV4-6.0-SA-F7P-6	A	B
FV4-6.0-SA-F7P-9	A	B
FV4-6.0-SUG-F7P	A	B
FV4-6.0-SUG-F7P-2	A	B
FV4-6.0-SUG-F7P-4	A	B
FV4-6.0-SUG-F7P-5	A	B
FV4-6.0-SUG-F7P-6	A	B
FV4-6.0-SUG-F7P-9	A	B
FV4-6.0-SUR-F7P	A	B
FV4-6.0-SUR-F7P-2	A	B
FV4-6.0-SUR-F7P-4	A	B
FV4-6.0-SUR-F7P-5	A	B
FV4-6.0-SUR-F7P-6	A	B

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
FV4-6.0-SUR-F7P-9	A	B
FV4-6.0-UBW-F7P	A	B
FV4-6.0-UBW-F7P-2	A	B
FV4-6.0-UBW-F7P-4	A	B
FV4-6.0-UBW-F7P-5	A	B
FV4-6.0-UBW-F7P-6	A	B
FV4-6.0-UBW-F7P-9	A	B
OR4-2.3-RGB-F7P	B	C
OR4-2.3-RGB-F7P-2	B	C
OR4-2.3-RGB-F7P-4	B	C
OR4-2.3-RGB-F7P-5	B	C
OR4-2.3-RGB-F7P-6	B	C
OR4-2.3-RGB-F7P-9	B	C
OR4-2.75-RGB-F7P	B	C
OR4-2.75-RGB-F7P-2	B	C
OR4-2.75-RGB-F7P-4	B	C
OR4-2.75-RGB-F7P-5	B	C
OR4-2.75-RGB-F7P-6	B	C
OR4-2.75-RGB-F7P-9	B	C
OR4-4.0-WHT-F7P	B	C
OR4-4.0-WHT-F7P-2	B	C
OR4-4.0-WHT-F7P-4	B	C
OR4-4.0-WHT-F7P-5	B	C
OR4-4.0-WHT-F7P-6	B	C
OR4-4.0-WHT-F7P-9	B	C
OR4-6.0-WHT-F7P	B	C
OR4-6.0-WHT-F7P-2	B	C
OR4-6.0-WHT-F7P-4	B	C
OR4-6.0-WHT-F7P-5	B	C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1068

Issue Date: 10/3/2024

Parts Affected	Old Rev.	New Rev.
OR4-6.0-WHT-F7P-6	B	C
OR4-6.0-WHT-F7P-9	B	C
R25-2.3-RGB	D	E
R25-2.75-RGB	D	E
R25-4.0-WHT	D	E
R25-5.0-RGB	D	E
R25-6.0-WHT	D	E

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The drawing views and dimensions of the assembly product have been adjusted due to the updated lens cap component used. (c.f. new dimension on the drawing)

Effective Date of Change: October 3, 2024

Reason for Change: The changes made to the lens cap were intended to enhance the product's performance and quality.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.