




PRODUCT CHANGE NOTIFICATION

MAGNETICS



Bourns® Model PAD001/002, PS13005, PT131xxL, PT610xxPEL, PT76787PEL, SM13xxxEL/XEL/CEL/PEL, SM51xxxPEL/EL and SM75xxxPEL Series SMD Transformers

Relocation of Manufacturing Site

Riverside, California – February 9, 2024 – In order to enhance uninterrupted continuity of supply, effective January 22, 2024, Bourns changed the place of manufacture for the Model PAD001/002, PS13005, PT131xxL, PT610xxPEL, PT76787PEL, SM13xxxEL/XEL/CEL/PEL, SM51xxxPEL/EL and SM75xxxPEL Series SMD Transformers.

A list of affected part numbers is provided below.

Affected Part Numbers		
PAD001-T764117S	PT61018PEL	SM13126PEL
PAD001-T764120S	PT61020EL	SM13139EL
PAD002-T764111S	PT61021XEL-5	SM13142EL
PAD002-T764113S	PT61022XEL	SM13143EL
PS13005	PT76787PEL	SM51589PEL
PT13113L	SM13043EL	SM51594EL
PT13124L	SM13047XCEL	SM51607EL
PT13141L	SM13064EL	SM51612EL
PT13144L	SM13077XEL	SM51625EL
PT61017PEL	SM13086CEL	SM75056PEL
PT61017XPEL	SM13112EL	SM75057PEL
PT61017XPEL-1	SM13117EL	SM75858PEL

The form, fit, function, quality, and reliability of the transformers will not change. The change of manufacturing location will not change the data sheet specifications for the affected transformer models. The country of origin for the affected part numbers will not change. The production lead time of these transformers will remain the same. Traceability will be maintained through lot code and date code.

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC24028

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance.

To assure an orderly transition of the production location and customers with the existing backlog, a hold was placed on deliveries of the affected part numbers from the previous manufacturing location.

Implementation dates are as follows:

Date that deliveries of products manufactured at the old manufacturing location ceased: ***December 4, 2023***

Date deliveries of products manufactured at the new manufacturing location began: ***January 22, 2024***

First date code for such deliveries from new manufacturing site: ***2404***

If you have any questions or need additional information, please feel free to contact [Bourns Customer Service/Inside Sales](#).