

Attn.: _____

HIROSE ELECTRIC CO., LTD.
2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, JAPAN

JR13W-3-core, JRC21-17-core receptacle, HR08-42-core receptacle Additional hole in soldering area

We are writing today to inform you that we will make some changes as shown in the subject for the reason described below.

We will announce them in advance.

1	Products	JR13W-3-core JRC21-17-core receptacle HR08-42-core receptacle *Please refer to the attachment 1 for detailed product names.
2	Substitute proposal product	JR13W-3-core JRC21-17-core receptacle HR08-42-core receptacle *Please refer to the attachment 1 for detailed product names.
3	Classification of change	Product specification change.
4	Changes	A plating hole will be added to the terminal. Please refer to the attachment 2 for details. These changes will not affect the performances of the product.
5	Reason for change	To improve productivity.
6	Date of final reception of orders for the applicable product	September 30,2025
7	Date of the first reception of orders for the substitute proposal product	November 20,2024
8	Date of final shipment of the applicable product	March 31,2026
9	Estimated order quantity of applicable products	Please contact our sales representative by November 29, 2024 with the expected number of orders to be placed by the final order date.
10	Date of your acknowledgement	By February 28,2025

Due to unavoidable circumstances such as future material supply conditions, orders for the applicable products may be terminated without prior notice prior to the final order acceptance date.

We apologize for the inconvenience, but we kindly ask that you please inform our sales representative as soon as possible of your approval.

Please note that if we do not receive a response by the approval date, we will assume that your approval has been received, and if you receive an order for the applicable product after the final order acceptance date, we will not be able to accept your order.

If you should have any questions, please feel free to contact a Hirose business representative.
Your understanding and cooperation are highly appreciated.

■Product list PCN2024-08_JR13W-3-core, JRC21-17-core receptacle, HR08-42-core receptacle Additional hole in soldering area


No.	Current product		Substitute proposal product		Remarks	
	Product code	Product name	Product code	Product name	Before	After
1	CL0114-2101-0-00	JR13WPFA-3SA	CL0114-2101-0-20	JR13WPFA-3SA(20)	Without plating holes	With plating holes
2	CL0114-2103-0-00	JR13WRFA-3PA	CL0114-2103-0-20	JR13WRFA-3PA(20)		
3	CL0114-2106-0-00	JR13WR-3PA	CL0114-2106-0-20	JR13WR-3PA(20)		

*JRC21 and HR08 are not included in this list because they are limited to certain companies.

Changes : Additional plating loop hole in terminal soldering area

Air bubbles and other bubbles accumulate in the plating process at the soldering area of terminals, causing process defects that do not allow sufficient plating to be applied. Therefore, to improve productivity, plating loop holes are provided and the shape of terminals is changed.

Terminal Shape Change Details



Acknowledgement

(Customer → Hirose Electric business representative)

JR13W-3-core, JRC21-17-core receptacle, HR08-42-core receptacle
Additional hole in soldering area

We acknowledge the changes and schedule of this notification.

Customer's name: _____

Acknowledgement stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.

(Cut on this line)

Document Receipt

(Customer → Hirose Electric business representative)

JR13W-3-core, JRC21-17-core receptacle, HR08-42-core receptacle
Additional hole in soldering area

We received the document concerning the above.

Customer's name: _____

Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.