

**Document Receipt Acknowledgement**

Date:  
Section:  
Name:



Document Number: D07718-A-G0040

Date: Jun. 15, 2024

Attention:

**ANGLIA COMPONENTS LTD**

**Request for approval for alternative production at Yokaichi factory  
due to impact of earthquake to Anamizu factory**

Winding type Common mode choke coil DLW5A/DLW5B series

Chip inductor LQH2HNNH\_03, LQH2HPN/Z/H\_GR, LQH2HPZ\_JR, LQH32NZ/H\_23, LQH3NPN/Z/H\_ME, LQH43CN\_03,  
LQH43NN/Z/H\_03, LQH43PN/Z/H/B\_26 series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.  
This is the official notification that some of our products detailed below.  
Your understanding and support are highly appreciated.

**1. Product Type and Customer/Murata Part Numbers:**

Product Type: DLW5A/DLW5B series

LQH2HNNH\_03, LQH2HPN/Z/H\_GR, LQH2HPZ\_JR, LQH32NZ/H\_23, LQH3NPN/Z/H\_ME, LQH43CN\_03,  
LQH43NN/Z/H\_03, LQH43PN/Z/H/B\_26 series

Please refer to the attached documents for Part Numbers' information.

**2. Background/Request:**

These series are produced at Anamizu Murata Manufacturing Co., Ltd. (Anamizu Factory).  
The Anamizu factory was affected by the 2024 Noto Peninsula earthquake that occurred on  
January 1, 2024.  
We have been working to restore the plant after May as soon as possible, but we are starting  
production on May 13th.  
In addition, we will restart production in order at Anamizu factory for products which was  
produced temporarily in Murata Manufacturing Company, Ltd. Yokaichi Plant (Yokaichi Factory)  
also .  
Thank you for your understanding in supplying the restarted products at the Anamizu Factory.

Please note that there are no changes for 4M (Man, Machine, Material, Method).

**3. Contact Window:**

Should you have any questions or concerns,  
please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Marketing & Promotion Department EMI Filter Division  
Hiromi Nagasaka