THALES

ID No. 864 Proc	uct/Process Change Notifica	Date 21.01.2022	
Product	Ordering Code	•	
PLS83-J Rel.1.0	L30960-N6590-A100		
PLS83-W Rel.1.0	L30960-N6530-A100		
PLS63-W Rel.1.1	L30960-N6520-A101		
Ordering Code changes:	☐ Yes	☐ Yes ☐ No	
Product	New Ordering Code	New Ordering Code	
Reason of Change: ☐ Technical requirement ☐ Change of production process/logistical changes ☐ Customer requirement ☐ Quality improvement ☐ Other:			
Description of change:	Thales introduce an additional factory in Vietnam for PLS63 and PLS83 to increase production and delivery capability. According to the standards this is visible on the labels. "Made in Vietnam V" The production of listed modules will run in parallel in both factories.		
Schedule details:	CW6/YEAR2022		
Availability of SW for evaluation:	NA		
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW13/2022		
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.		
Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.		

Attachments:



2022/1/26 27.01.2022

X WANG JIANFENG

X i. Valaduaun

Product Program Manager Signed by: WANG Jianfeng Vice President Quality Management Signed by: ERDMANN Joerg