

#### 1 Products affected

Product hierarchy no. *			y no. *	Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
02	007	012	0000002051	See appendix below	Appliance inlet	4798	-


<sup>\*</sup>SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected for type 6600-5							
4798.9000	4798.9100	4798.9200	3-100-550	3-100-595			
3-102-236	3-108-420						

### 2 Type of change

- Change of label
- Change of configuration code

## 3 Detailed description of change



• Change of Configuration Code and therefore change on label

#### 4 Reason of change

Added digit to the Configuration Code for enlargement of product range in the future.

#### 5 Release date

The change takes effect in ww 31/2024 (Date code 2431 or higher on label).

## 6 Impact of change and recommended action

	Form	No action
	Fit	No action
	Function	No action
П	Manufacturing	No action

☐ Packaging No action

Product Change Notification						4798 Change of Configuration Code		
owner	creation date	release date	released by	change order	rev	page	D40 002 402	
sariogar	17.05.2024	29.05.2024	muehlema	2027836	Α	1 of 2	D10-083-182	





# 7 Reference Documents

Kind of document	Document Title
Data Sheet	Data Sheet 4798

Product CI	hange Notifi	cation		4798 Change of Configuration Code				
owner	creation date	release date	released by	change order	rev	page	D10-083-182	
sariogar	17.05.2024	29.05.2024	muehlema	2027836	Α	2 of 2		