

1 Products affected

Product hierarchy no. *				SBU	Part. no.	Configuration code
SBU	PG	PUG	Type			
80	081	002	0000006042	EMC	DFKH-22-0001	DFKH2-22-0.45-40/A
					DFKH-22-0002	DFKH2-22-1.0-20/A
					DFKH-22-0003	DFKH2-22-2.0-6.0/A
					DFKH-22-0004	DFKH2-22-4.0-1.5/A
					DFKH-22-0005	DFKH2-22-6.3-0.6/A


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Terminal pins changed

3 Detailed description of change

- Rectangular pins substituted with round pins



4 Reason of change

- Standardization of choke cases
- Optimize assembly process

5 Release date

The change will be rolled-out starting wk 14/2024 (Date code 2414 or higher on label) and lasts approx. 6 months.

6 Action

Form	Yes	Check PCB pin hole dimension and tolerances
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					PCN DFKH-22 Terminal pins changed		
owner	creation date	release date	released by	change order	rev	page	D10-080-722
segatro	15.01.2024	18.03.2024	blumhe	2027294	A	1 of 1	