

1 Products affected

Product hierarchy no. *				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
02	006	6016	0000001533	See appendix	Connector	KMF	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected for type KMF				
KMF1.1293.11	KMF1.1193.1103	KMF1.1123.1101	KMF0.2163.11	3-134-743
KMF1.1263.11	KMF1.1193.11	KMF1.1123.11	KMF0.2143.11	3-127-408
KMF1.1243.11	KMF1.1163.11	KMF1.1113.11	KMF0.2123.11	3-122-687
KMF1.1223.11	KMF1.1143.11	KMF0.2293.11	KMF0.2113.11	3-101-048
KMF1.1213.11	KMF1.1123.1102	KMF0.2193.11	3-148-880	


2 Type of change

- Change of label

3 Detailed description of change

Current label	New label

Product Change Notification					PCN KMF Resistor position		
owner	creation date	release date	released by	change order	rev	page	D10-080-140
seilerra	06.12.2023	24.01.2024	blumhe	2027340	A	1 of 2	



- The bleed resistor is placed closer to the X-capacitor.

4 Reason of change

- Improved safety

5 Release date

The change takes effect in ww 04/2024 (Date code 2404 or higher on label).
Parts on stock will be used upon depletion.

6 Impact of change and recommended action

- Form
- Fit
- Function no action required
- Manufacturing
- Label no action required
- Packaging

7 Reference Documents

Kind of document	Document Title
KMF	PCN KMF Change of Bleed Resistor Position

Product Change Notification					PCN KMF Resistor position		
owner	creation date	release date	released by	change order	rev	page	D10-080-140
seilerra	06.12.2023	24.01.2024	blumhe	2027340	A	2 of 2	