

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBL	J PG	PGU	Туре				
01	002	030	000000522	See list below	Circuit Protection	OGN-SMD	-

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of affected part numbers


0031.8305	0031.8306	0031.8307	0031.8308	0031.8309	0031.8310	0031.8311	0031.8312
0031.8313	0031.8314	0031.8315	0031.8316	0031.8317	0031.8318	0031.8319	0031.8320
0031.8321	0031.8322	0031.8323	0031.8324	0031.8325	0031.8326	0031.8327	0031.8413
0031.8414	0031.8415	0031.8416	0031.8417	0031.8418	0031.8419	0031.8420	0031.8421
0031.8422	0031.8423	0031.8424	0031.8425	0031.8426	0031.8501	0031.8502	0031.8503
0031.8504	0031.8505	0031.8506	0031.8507	0031.8508	0031.8509	0031.8510	0031.8511
0031.8512	0031.8513	0031.8514	0031.8515	0031.8516	0031.8517	0031.8518	0031.8519
0031.8601	0031.8701	0031.8923	0031.8925	0031.8920	0031.9001		

2 Type of change

Packaging improvement: New color of the carrier tape.

3 Detailed description of change

Color change of the carrier tape



4 Reason of change

The supplier changed the color.

OGN-SMD						2192	
creation date	created by	release date	released by	notification no.	revision	page	
2013-10-31	dislercy	2013-12-19	dislercy	25389	_	1 of 2	



5 Release date

The change will be rolled-out starting in June 2014. However, the exact date of the change depends on the inventory and turnover of the individual variants.

6 Impact of change and recommended action

Form:	no
Fit:	no
Function:	no
Production Site:	no
Product Label:	no

7 Reference Documents / Attachments

Kind of document	Document number	Remarks	
0118.2192.001	Excel list with affected	0118.2192.001.xls	
	part numbers		
Data Sheet	OGN-SMD	Web Link OGN-SMD	

	0118.2192					
creation date	created by	release date	released by	notification no.	revision	page
2013-10-31	dislercy	2013-12-19	dislercy	25389	_	2 of 2