



**PROTECT  
CONTROL  
SENSE**




# Packaging Update for 881 Series Parts

Jan 2022

 **Littelfuse**<sup>®</sup>  
Expertise Applied | Answers Delivered

# Changes

- Internal MBB package bag update from thickness 0.8mm to 1.0mm  
add PET in bag surface to sure it's permeable rate can match MSL2a



- Add Humidity indicator in inside package to check the humidity result for product.
- Add MSL2a logo in print label

# New Packaging Condition

Metal Barrier Bag

Reeled Fuses  
(Inside MBB)

Dessicant

Humidity Indicator  
Card (Inside MBB)



MSL Label

NOTE: Metal Barrier Bag is  
vacuum sealed

# Scope of Change

---

- This change scope affects all 881 series product contains the following P/Ns.

0881060.UR	0881080.UR	0881060.UR-ER	0881100.UR-ER
0881070.UR	0881080.UR-ER	0881070.UR-ER	0881100.URF
0881080.UR	0881080.URF	0881070.URF	0881100.URSD
0881090.UR	0881080.UR		
0881100.UR	0881080.UR-ER		