



Product/Process Change Notice - PCN 16_0169 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

PCN Title: AD9154 Die Revision and Data Sheet Update
Publication Date: 01-Sep-2016
Effectivity Date: 30-Nov-2016 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

Die Revision Changes:
- Rewire charge pump circuitry to increase the initial charge pump voltage.

Reason For Change

Die Revision Changes:
- The change addresses an issue where at cold temperatures, the on-chip phase-locked loops (PLLs) for either the SERDES or DAC clock PLLs may not lock from startup due to a low initial charge pump voltage.

Impact of the change (positive or negative) on fit, form, function & reliability

There is no change to the fit, form and reliability of the devices.
The functionality is improved with the revision when attempting to lock the SERDES and/or DAC PLLs at cold temperatures. The SERDES or DAC clock PLL will always lock at cold temperatures.

Product Identification *(this section will describe how to identify the changed material)*

The Revision ID Register Address 0x06 default value changes from 0x89 to 0x99 for silicon revision traceability.
Changes will be reflected in the Rev. C of the AD9154 data sheet.

Summary of Supporting Information

Due to minor nature of the change, no qualification testing is required.

Supporting Documents None

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN_Americas@analog.com	Europe: PCN_Europe@analog.com	Japan: PCN_Japan@analog.com
		Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Added Parts On This Revision - Product Family / Model Number (4)

AD9154 / AD9154BCPAZ

AD9154 / AD9154BCPAZRL

AD9154 / AD9154BCPZ

AD9154 / AD9154BCPZRL

Appendix B - Revision History

Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	01-Sep-2016	30-Nov-2016	Initial Release

Analog Devices, Inc.

DocId:3792 Parent DocId:3780 Layout Rev:7