


## PRODUCT CHANGE NOTIFICATION

**Date Issued:** December 9, 2019

**Product Identification:** Bel 0863, 0864, 0873 2x4, 2x6, 2x8 ICMs

**PCN Number:** PC2190135

**Reason for Change (s):** In an effort to continually improve our product, Bel is pleased to announce a modification to the front shield of the 0863, 0864 and 0873 2xN ICMs in the specific area of the light-pipe and front shield. As shown below the gap between the light-pipe and shield is too small and can cause the shield to bend or become misaligned and create a snagging hazard. The solution is to remove the thin window frames from around the inside and bottom of the light-pipe.



The affected part numbers are:

All 0863-2xxR-xxx part numbers


All 0864-2xxR-xxx part numbers

All 0873-2xxR-xxx part numbers


These changes will not affect “form, fit, or function”, nor do they affect any other dimensions or electrical parameters of the part. No other related changes to the above series are being implemented at this time.

**Description of the Change (s):** To resolve the assembly issue and deformation of the shield around the light-pipe, the thin, shield window frames around the inside and bottom of the light-pipe will be removed. By removing these thin metal pieces, the limited gap issue will be resolved and there will not be a concern for shield deformation. Please see the details below.

Old finished goods



New finished goods: remove the LED window features.




**Planned Timing and Implementation of Change:** This change will be implemented on any new orders after January 1, 2020.

**Impact on Quality and Reliability:** None.

**Availability of Qualification Data:** None.

**Remarks:** None.

**Signature:** John Hess, ICM Product Manager

A handwritten signature in black ink, appearing to read 'R. Hess', with a long horizontal line extending to the right.

**(Bel Representative)**

*Note: This form should only be used for advising the customer.*