


Product Change Notification

INDUCTIVE COMPONENTS



August 9, 2018

Bourns® Part Number SRP1250-6R0MA and SRP1270-2R2M Shielded Power Inductors

Change to Removal Process of the Magnetic Wire Insulation

Effective immediately, Bourns is changing the removal process of the magnetic wire insulation in part numbers SRP1250-6R0MA and [SRP1270-2R2M](#) from a semi-automated machine to an automated laser machine. Utilizing a laser technology helps enable a thorough removal of the wire coating.

The manufacturing process change will not affect the inductor's form, fit or function. The quality and reliability of the inductor should be improved.

| Affected Part Numbers |
|-----------------------|
| SRP1250-6R0MA |
| SRP1270-2R2M |

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).