



Select Radial Lead RF Choke Packaging Method Change

Model RL875 Series

Riverside, California – June 2, 2020 – Effective July 4, 2020, Bourns is changing the packaging method of the [Model RL875 Series Radial Lead RF Choke](#) to better protect the components from damage during transit and handling. Currently, the packaging consists of five components per styrofoam tray slot. This will be changed to one component per plastic tray slot.

The packaging change will not affect the form, fit, function or quality of the choke. The reliability of the component should be improved. A list of affected part numbers is included on the following page.

Current Packaging	Revised Packaging
	
Five components per styrofoam tray slot	One component per plastic tray slot

Implementation dates are as follows:

Date that products in existing package will cease: **July 4, 2020**

Date that deliveries of products in modified package will begin: **July 5, 2020**

First date code using the above changes: **2028**

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC2039

Affected Part Numbers

RL875-100M-RC	RL875-121K-RC	RL875-180K-RC	RL875-222K-RC	RL875-331K-RC	RL875-470K-RC	RL875-562K-RC	RL875-822K-RC
RL875-101K-RC	RL875-122K-RC	RL875-181K-RC	RL875-270K-RC	RL875-332K-RC	RL875-471K-RC	RL875-680K-RC	RL875-821K-RC
RL875-102K-RC	RL875-150K-RC	RL875-182K-RC	RL875-271K-RC	RL875-390K-RC	RL875-472K-RC	RL875-681K-RC	
RL875-103K-RC	RL875-151K-RC	RL875-220K-RC	RL875-272K-RC	RL875-391K-RC	RL875-560K-RC	RL875-682K-RC	
RL875-120M-RC	RL875-152K-RC	RL875-221K-RC	RL875-330K-RC	RL875-392K-RC	RL875-561K-RC	RL875-820K-RC	