

## Product Change Notification

INDUCTIVE COMPONENTS



May, 2015

### 8100 Common Mode Choke Series Shipping Package Modification & Order Quantity Adjustment

The shipping package of the Bourns® [Model 8100 Series](#) Common Mode Chokes has been redesigned to provide better component protection for normal shipping and handling environments. The original shipping package (Figure 1) offers more limited protection for the components against shock and vibration commonly encountered during shipping and handling processes than the new modified package.

The new modified package (Figure 2) is a portioned plastic tray designed to fit to the contour of each component. Each component is individually placed in a cavity which provides excellent protection against component shifting and tumbling during shipping and handling processes. This new plastic tray package has successfully passed the container drop-test.



Figure 1




Figure 2

As a result of the shipping package modification, the Minimum Order Quantity (MOQ) and Multiple Ordering Quantities (MULT) of several part numbers have been adjusted. Please refer to the part number list in Table 1 for the implementation dates and the adjusted order quantities.

The form, fit, function, quality and reliability of the components are not affected. Only the packaging and ordering quantities have been modified.

**Table 1** - Implementation dates and new quantities are as follows:

Part Number	Implementation Date/ Date Code	Current Order Quantity		Revised Order Quantity	
		MOQ	MULT	MOQ	MULT
8101-RC	August 24, 2015 / 1530	220	110	315	315
8102-RC	August 24, 2015 / 1530	220	110	315	315
8103-RC	August 24, 2015 / 1530	220	110	315	315
8104-RC	August 24, 2015 / 1530	286	143	360	360
8105-RC	August 24, 2015 / 1530	286	143	360	360
8106-RC	August 24, 2015 / 1530	286	143	360	360
8107-RC	August 24, 2015 / 1530	286	143	360	360
8108-RC	August 24, 2015 / 1530	286	143	360	360
8109-RC	August 24, 2015 / 1530	216	216	240	240
8110-RC*	March 2, 2015 / 1510	240	240	240	240
8111-RC	August 24, 2015 / 1530	216	216	240	240
8112-RC	August 24, 2015 / 1530	216	216	240	240
8113-RC	August 24, 2015 / 1530	243	243	270	270
8114-RC	August 24, 2015 / 1530	243	243	270	270
8115-RC	August 24, 2015 / 1530	243	243	270	270
8116-RC	August 24, 2015 / 1530	216	216	192	192
8117-RC	August 24, 2015 / 1530	216	216	192	192
8118-RC	August 24, 2015 / 1530	168	168	168	168
8119-RC	August 24, 2015 / 1530	168	168	168	168
8120-RC*	March 2, 2015 / 1510	168	168	168	168
8121-RC	August 24, 2015 / 1530	168	168	168	168

\* Bourns has already implemented the changes to the new packaging method.

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).