


Engineering Change Notice

Part No. <u>3568-10, -15, -20</u>	ECN No. <u>23-030</u>
Part Name <u>FUSE HOLDER</u>	Date <u>3.06.23</u>
Rev. <u>A</u>	ECR No. <u>—</u>

Description of Change: Drawing Attached
FUSE CLIP WAS WRONG SIZE, REPLACE FUSE CLIP ON CORRECT ONE.

Solution: Tooling Change Required
REVISE C+M DWG


Disposition of Parts:
U.A.I.

Signed  Date 3.06.23

Required Distribution:

Engineering Quality Control Purchasing Manufacturing/Supplier

Chief Engineer: **Remarks:**

Signed  Date 3.06.23

Document Control: Rev. B

Change Incorporated Signed NATASHA T. Date 3.06.23