


Engineering Change Notice

Part No. <u>3568</u>	ECN No. <u>23-031</u>
Part Name <u>FUSE HOLDER</u>	Date <u>3.06.23</u>
Rev. <u>C</u>	ECR No. <u>—</u>


Description of Change: Drawing Attached
FUSE CLIP WAS WRONG SIZE, REPLACE FUSE CLIP ON CORRECT ONE.

Solution: Tooling Change Required
REVISE C+M DWG

Disposition of Parts:
U.A.I.

Signed  Date 3.06.23

Required Distribution:
 Engineering Quality Control Purchasing Manufacturing/Supplier

Chief Engineer: **Remarks:**
Signed  Date 3.06.23

Document Control: **Rev.** **Signed** **Date**
 Change Incorporated D NATASHA T. 3.06.23