



Expertise Applied | Answers Delivered

Littelfuse, Inc.
8755 West Higgins Road, Suite 500
Chicago, IL 60631 USA
(773) 628-1000

October 10, 2018

RE: Littelfuse HWB18 & HWB60 Supply Change

Dear Valued Customer,

To better serve our customers by increasing responsiveness and flexibility, during Q42018, we will change our manufacturing locations for plastic components associated with the HWB18 and HWB60, from an outside injection molding supplier to a Littelfuse injection molding facility.

The affected Littelfuse finished good part numbers are:

PDM21001LXM	PDM31002ZXM
PDM21002LXM	PDM31003ZXM
PDM21005LXM	PDM31004ZXM
PDM31001ZXM	

New quality and PPAP documentation will be prepared upon completion of the transfer and available upon request.

Please let myself or your Littelfuse sales contact know if you have any questions or concerns.

Regards,

A handwritten signature in black ink that reads "Joe Plazyk" in a cursive script.

Joe Plazyk
Global Product Manager
Automotive Business Unit, Commercial Vehicle Products
Littelfuse, Inc.
JPlazyk@littelfuse.com