

## Product Code Change

Issue Date  
January 07, 2015

No. CS-L-1501001

Tactile switches


The modifications of manufacturing country and product code change for B3FS series.

### [ Effective Date ]



Effective as of July 1, 2015

### [ Changes ]

Models	Old Product Code	New Product Code
B3FS-1050	B3FS1031F	B3FS6001A
B3FS-1052	B3FS1035R	B3FS6002M
B3FS-1005	B3FS0010H	B3FS1126F
B3FS-1015	B3FS0008F	B3FS1127D
B3FS-1010	B3FS1025A	B3FS1128B
B3FS-1012	B3FS1024C	B3FS1129M
B3FS-1000	B3FS2000A	B3FS1130D
B3FS-1002	B3FS2002H	B3FS1131B
B3FS-1002P	B3FS1002B	B3FS1132M



### [ Other Changes ]

Before the change	After the change
<p><b>The country of origin.</b> MADE IN JAPAN</p> <p><b>The display of a packing label on reel.</b> <b>Production factory abbreviation change</b> Lot No □□□□R□</p> <p><b>Display of the country of origin.</b> MADE IN JAPAN</p>  <p>□□□□R□      MADE IN JAPAN</p>	<p><b>The country of origin.</b> MADE IN CHINA</p> <p><b>The display of a packing label on reel.</b> <b>Production factory abbreviation change</b> Lot No □□□□C□</p> <p><b>Display of the country of origin.</b> MADE IN CHINA</p>  <p>□□□□C□      MADE IN CHINA</p>

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.