

Product change notification (PCN)

Title / short description	Changed component position
Affected article category	Terminal blocks
Change category	Form and appearance
Change number	CBE180154-06

Purpose/objective of the change

Changed connection of the components between the current bars

Detailed description of the change

The components previously positioned vertically in the housing will be positioned horizontally in the future. Furthermore, the current bars will be thermally caulked.

Identifying characteristics

Components positioned horizontally in the housing. Furthermore, the current bars are thermally caulked.

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2019-12-09	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input checked="" type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- CBE180154.pptx
- Material_list.csv
- PCN-CBE180154-06 Veränderte Position Bauelement_DE
- PCN-CBE180154-06 Changed component position_EN

Material list

Item	Article Type	Revision/production batch		Item	Substitute item Type
		old	new		
3031563	STTB 2,5-DIO/U-O				
3031555	STTB 2,5-DIO/O-U				
3030938	STTB 2,5-R499/O-U				
3035399	STTB 2,5-R20K/O-U OG				
3031564	STTB 2,5-DIO.1N5408K/U-O				