

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.	
SBU	PG	PUG	Type					
01	002	063	0000000595	0031.1611	Circuit Protection	FEC fuse carrier 5x20	n/a	
				0031.1613		FEC fuse carrier 6.3x32	n/a	
				0031.1621		FEC fuse holder 5x20	n/a	
		003		0000000527		0031.1632	FEC fuse holder 5x20	n/a
						0031.1622	FEC fuse holder 6.3x32	n/a
						0031.1633	FEC fuse holder 6.3x32	n/a


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of markings

3 Detailed description of change

Change the markings on the slotted fuse carrier cap.



4 Reason of change

- Better readability of the markings

5 Release date

The change will be rolled-out starting ww 41/2020 (Date code 2041 or higher on label).

6 Impact of change and recommended action

Form	Yes	Markings changed
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	FEC fuse holder
Data Sheet	FEC fuse carrier

Product Change Notification					FEC cap inscription		
owner	creation date	release date	released by	change order no	rev	page	D10-040-163
dislercy	07.10.2019	17.06.2020	bucherfa	2018489	A	1 of 1	