

1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PUG Type				
			0700 /	
02 005 016 0000001210	See list below	Connectors	6762 (screw-on)	

List of part numbers affected						
3-100-970	4304.4104	4304.6055	4304.6061	4304.6162		
4304.4100	4304.6049	4304.6057	4304.6070	4304.6224		
4304.4101	4304.6052	4304.6058	4304.6071			
4304.4102	4304.6053	4304.6059	4304.6152			
4304.4103	4304.6054	4304.6060	4304.6157			

2 Type of change

- 1. Change of approval markings from UR and CSA to the combined cURus on the product socket according to standard update of UL/CSA 60320-1
- 2. Backside of flange with ribs and less material

3 Detailed description of change



4 Reason of change

- 1. The change is due to a standard update to UL/CSA 60320-1
- 2. To improve the moulding process and to avoid flow lines

5 Release date

The change takes effect in ww 19/2020 (Date code 2019 or higher on label) and last approx. 6 months depending on the variant and stock. This change has no effect on the validity of the approval certificates

Product Change Notification				PCN 6762 (screw-on)			
owner	creation date	release date	released by	change order no	rev	page	D10 012 010
huberth	19.03.2020	26.03.2020	muehlema	2019628	Α	1 of 2	D10-043-840



6 Impact of change and recommended action

Form Yes 1. Socket new with cURus approval marking

Form Yes 2. Less material and new a rib construction on the backside of flange

Fit No No change for dimension Function No No change in function

Manufacturing No No change for manufacturing site

Label No No change on label
Packaging No No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 6762	

Product Change Notification				PCN 6762 (screw-on)				
owner	creation date	release date	released by	change order no	rev	page	D40 042 040	
huberth	19.03.2020	26.03.2020	muehlema	2019628	Α	2 of 2	D10-043-840	