

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	005	012	0000001155	8843.0901	Connectors	8843 FUSEHOLDER 6.3x32 10A	n/a
02	005	012	0000001155	8843.0902	Connectors	8843 FUSEHOLDER 5x20 10A	n/a

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

Change of packaging quantity and approval marks from CSA and UR to combined cURus on the packaging Label.

3 Detailed description of change

Old label	New label

4 Reason of change

- Packaging unit changed from 100 pieces to 20 pcs for logistical reasons.
- Standards update according to the new UL/CSA 60320-1.

5 Release date

The change will be rolled-out starting ww 36/2020 (Date code 2036 or higher on label) and lasts approx. 3 months depending on the variant.

6 Impact of change and recommended action

Form	No	-
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	Yes	Change on label
Packaging	Yes	Change in packaging

Product Change Notification					8843.0 Fuseholder change of packing quantity		
owner	creation date	release date	released by	change order no	rev	page	D10-047-562
sariogar	12.08.2020	20.08.2020	blumhe	2020441	A	1 of 1	