

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
80	084	001	0000006145	See list below	EMC	FMAB-72	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
5500.2021	5500.2024	5500.2107	5500.2110	5500.2113
5500.2022	5500.2025	5500.2108	5500.2111	5500.2114
5500.2023	5500.2106	5500.2109	5500.2112	5500.2115

2 Type of change

Change tolerance of pins length

3 Detailed description of change

Tolerance of pins length from 3.5 +0/-0.5 to 3.5 +/-0.5.

Old mechanical drawing	New mechanical drawing

4 Reason of change

- Previously indicated tolerances not accurate enough.

5 Release date

The change takes effect in ww 49/2017 (Date code 1749 or higher on label).

6 Impact of change and recommended action

Form	No	No change in form
Fit	Yes	Change of pin length
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet FMAB-72	

Product Change Notification					PCN FMAB-72 Family - Pins lenght		
owner	creation date	release date	released by	change order no	rev	page	D10-021-337
segatro	13.12.2017	13.12.2017	stornifa	2014362	B	1 of 1	