

1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.			
SBU PG PUG Type							
80 084 002 0000006504	See list below	EMC	FMLB-51				
80 084 002 0000006149	See list below	EMC	FSW-65				
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)							


List of part numbers affected							
5500.2035	5500.2036	5500.2037	5500.2038	5500.2082	5500.2083		
5500.2084	5500.2085	5500.2094	5500.2095	5500.2096	5500.2097		
5500.2058	5500.2059	5500.2060	5500.2061	5500.2062	5500.2063		


2 Type of change

- Nickel plated steel case instead of aluminium case
- Different shape of external quick connect terminals
- Change of production site

3 Detailed description of change


- Change of product appearance due to new nickel plated steel case instead of aluminium case
- Different shape of plastic part for external quick connector terminals
- Moved position and turned protective earth terminal to a vertical position
- New cases are provided with a bottom cover
- Change of factory code from SK to SC and origin from SK to CN on product and packaging labels





Product Change Notification				PCN FMLB-51 FSW-65 case 49 redesign				
owner	creation date	release date	released by	change order no	rev	page	D40 044 505	
segatro	04.12.2019	10.12.2019	canoniar	2018653	Α	1 of 2	D10-041-505	





4 Reason of change

- Improved filter performance due to completed closed steel case
- Reorganization of production process
- Production site transfer from Slovakia to China

5 Release date

The change will be rolled-out starting wk10/2020 (Date code 2010 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form Yes New material and different quick connect terminals

Fit Yes Earth terminal position
Function No No change in function
Manufacturing Yes Change of production site

Label Yes Change on label
Packaging No Change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
FMLB-51	
<u>FSW</u>	

Product Change Notification			PCN FMLB-51 FSW-65 case 49 redesign					
owner	creation date	release date	released by	change order no	rev	page	D10-041-505	
segatro	04.12.2019	10.12.2019	canoniar	2018653	Α	2 of 2		