

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|--------------------|--------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 01 | 001 | 025 | 0000000205 | See list below | Circuit Protection | USF 1206 0.5 A | n/a |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

| List of part numbers affected | | | |
|-------------------------------|--------------|--------------|--------------|
| 3413.0113.11 | 3413.0113.22 | 3413.0113.24 | 3413.0113.26 |

2 Type of change

- Change of marking
- Change of material

3 Detailed description of change

| Old product appearance | New product appearance |
|---|--|
|  |  |

4 Reason of change

- Symmetric marking to provide improved marking readability independent from device placement in blister.
- Change of body material due to material phase out.

5 Release date

The change takes effect in ww 03/2017 (Date code 2017 or higher on label).

6 Impact of change and recommended action

| | | |
|---------------|-----|---------------------------------------|
| Form | Yes | Changed marking and new body material |
| Fit | No | No change for dimension |
| Function | No | No change in function |
| Manufacturing | No | No change for manufacturing site |
| Label | No | No change on label |
| Packaging | No | No change in packaging |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|------------------|----------|
| Data Sheet | USF 1206 |

| Product Change Notification | | | | | | USF 1206 0.500 A, PCN | |
|-----------------------------|---------------|--------------|-------------|-----------------|-----|-----------------------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-012-696 |
| ganderka | 2017-01-13 | 2017-01-23 | nowakfr | 2011960 | A | 1 of 1 | |