

ID No. 882	Product/Process Change Notification		Date 28-03-2022	
Product	Orde	ering Code		
PLS63-W Rel1.1	L309	960-N6520-A101		
PLS83-W Rel1.1	L309	960-N6530-A101		
PLS63-W Rel2.0	L309	960-N6520-A200		
PLS83-W Rel2.0	L309	960-N6530-A200		
PLS63-EP Rel2.0	L309	960-N6560-A200		
PLS83-EP Rel2.0		960-N6570-A200		
Ordering Code changes:		′es 🛛 No		
Product		v Ordering Code		

Reason of Change:

- Technical requirement
- Customer requirement
- Quality improvement

Change of production process/logistical changes

 $\hfill\square$ Location of production moved

Other: module label change

Description of change:	Thales will deliver the products in the appendix list in the future with KC approval mark.	
	For example, PLS63-W	
	PLS63-EP	
	CINTERION S30960 56560 A200-1 Model: PIS63.BP Made in China S CC CINTERION S30960 56560 A101-1 Model: PIS63.BP Made in China S DC CINTERION S30960 56560 A101-1 Model: PIS63.BP Made in China S DC CINTERION S30960 S6560 A101-1 Model: PIS63.BP DC DC CINTERION S30960 S6560 A101-1 Model: PIS63.BP DC DC CINTERION S30960 S6560 A101-1 Model: PIS63.BP DC CINTERION S30960 S6560 A101-1 Model: PIS63.BP DC CINTERION S30960 S6560 A101-1 Model: PIS63.BP DC DC CINTERION DC DC CINTERION DC DC DC CINTERION DC DC CINTERION DC DC DC CINTERION DC DC DC DC DC DC DC DC DC DC	
	If there are further questions, our FAE team who offers comprehensive customer support, should be contacted.	
Availability of SW for evaluation:	NA	



Availability of modules ex warehouse:	May/2022
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
measurements.	Quality Management process and philosophy.

Attachments: no

2022/3/28

28.03.2022