


1 Products affected

Product hierarchy no.		Part no.	SBU	Product Type	Customer part no.		
SBU	PG	PUG	Туре				
01	001	1 023		3-139-122			-
				3-139-123	Circuit Protection	UHP	-
				3-139-124			-
				3-139-125			-
				3-139-126			-
			000000358	3-139-127			-
				3-139-128			-
				3-139-129			-
				3-139-130			-
				3-139-131			-
				3-139-132			-
				3-139-133			-

2 Type of change

- · Change of product marking
- Change of packaging label
- Change of data sheet

3 Detailed description of change



• UL file number E531402 added to data sheet

4 Reason of change

UL approval received

Product Change Notification					PCN UHP Change of product marking			
owner	creation date	release date	released by	change order	rev	page	D10-072-636	
hotiar	05.04.2023	06.04.2023	schulejo		Α	1 of 2		



5 Release date

The change takes effect in week 17/2023 (Date code 2317 or higher on label). Parts on stock will be used upon depletion.

6	Impact of change and	d recommended action
	□ Form	No action required, consider new marking at incoming inspection
	☐ Fit	
	☐ Function	
	☐ Manufacturing	
		No action required, consider new label information at incoming inspection
	☐ Packaging	

7 Reference Documents

Kind of document	Document Title
Data Sheet	UHP

Product Change Notification					PCN UHP Change of product marking			
owner	creation date	release date	released by	change order	rev	page	D40 070 606	
hotiar	05.04.2023	06.04.2023	schulejo		Α	2 of 2	D10-072-636	