

8755 W. Higgins Road Suite 500 Chicago, IL 60631

www.littelfuse.com

To: Littelfuse Sales, Sales Support & Customers Valued Customer

From: Littelfuse Product Management - Industrial Business Unit

Subject: Add CN Suffix to Solar Fuse product label manufactured at our Suzhou, China facility

Document Number: LFPCN_PG0130

Date: 10/25/2021

Regarding the above referenced, Littelfuse would like to inform you that there is an update to product labels of 0SPF, SPXI and SPXV Series Fuse manufactured at our Suzhou, China facility to include 'CN' Suffix information to match with our agency documentations. This change is only to the product label text printed and do not affect the construction or performance of the fuse.

Current Part Number Format	CN Added to Part Number	Comments
SPF 3DA - R	PF 30A – RO	Add CN to part number to 0SPF series for China Manufactured Products
Stoffus Carlos Fine (S) 32A - M	Influsor Finance 124 - MCN (2) 221 - MCN (2) 221 - MCN (2) 221 - MCN (2) 221 - MCN (2)	Add CN to part number to SPXV series for China Manufactured Products



Going forward / Timeframe

Please refer to page 3 on this document for a list of products related to this change.

The effective date of this running change is Nov 1st 2021.

I will appreciate if you could also send this e-mail to anyone else whom I could have un-intentionally missed out.

Thank you for your continued business. If you have any questions, or need additional information please contact our Littelfuse representative.

Sincerely,

Augusto Sánchez

Product Manager Industrial Business Unit Littelfuse, Inc.

Office: +52 878-784-4734 Techline: +1 800-TEC-FUSE www.littelfuse.com/electrical

List of products

OSPF Series
0SPF001.HXCN
0SPF001.HXRCN
0SPF001.TXCN
0SPF002.HXCN
0SPF002.HXRCN
0SPF002.TXCN 0SPF003.HXCN
0SPF003.HXCN
0SPF003.HXRCN 0SPF003.TXCN
0SPF003.TXCN
0SPF004.HXRCN
0SPF004.HXRCN
0SPF005.HXCN
0SPF005.HXRCN
0SPF005.TXCN
0SPF006.HXCN
0SPF006.HXRCN
0SPF006.TXCN
0SPF008.HXCN
0SPF008.HXRCN
0SPF008.TXCN
0SPF010.HXCN
0SPF010.HXRCN
0SPF010.TXCN
0SPF012.HXCN
0SPF012.HXRCN
0SPF012.TXCN
0SPF015.HXCN
0SPF015.HXRCN
0SPF015.TXCN
0SPF020.HXCN
0SPF020.HXRCN
0SPF020.TXCN
0SPF025.HXCN
0SPF025.HXRCN
0SPF025.TXCN
0SPF03.5HXCN
0SPF03.5HXRCN
0SPF03.5TXCN
0SPF030.HXCN
0SPF030.HXRCN
0SPF030.TXCN
557 1 555.17(6)(4

CDVI Ci
SPXI Series
SPXI001.LXCN
SPXI001.TXCN
SPXI002.LXCN
SPXI002.TXCN
SPXI003.LXCN
SPXI003.TXCN
SPXI004.LXCN
SPXI004.TXCN
SPXI005.LXCN
SPXI005.TXCN
SPXI006.LXCN
SPXI006.TXCN
SPXI008.LXCN
SPXI008.TXCN
SPXI010.LXCN
SPXI010.TXCN
SPXI012.LXCN
SPXI012.TXCN
SPXI015.LXCN
SPXI015.TXCN
SPXI016.LXCN
SPXI016.TXCN
SPXI02.5LXCN
SPXI02.5TXCN
SPXI020.LXCN
SPXI020.TXCN
SPXI025.LXBMCN
SPXI025.LXMCN
SPXI025.TXBMCN
SPXI025.TXMCN
SPXI03.5LXCN
SPXI03.5TXCN
SPXI030.LXBMCN
SPXI030.LXMCN
SPXI030.TXBMCN
SPXI030.TXMCN
SPXI032.LXBMCN
SPXI032.LXMCN
SPXI032.TXBMCN
SPXI032.TXMCN
SPXI04.5LXCN
SPXI04.5TXCN
SPXI2.25LXCN
1

SPXI2.25TXCN

SPXV Series
SPXV001.LXCN
SPXV001.TXCN
SPXV002.LXCN
SPXV002.TXCN
SPXV003.LXCN
SPXV003.TXCN
SPXV004.LXCN
SPXV004.TXCN
SPXV005.LXCN
SPXV005.TXCN
SPXV006.LXCN
SPXV006.TXCN
SPXV008.LXCN
SPXV008.TXCN
SPXV010.LXCN
SPXV010.TXCN
SPXV012.LXCN
SPXV012.TXCN
SPXV015.LXCN
SPXV015.TXCN
SPXV016.LXCN
SPXV016.TXCN
SPXV02.5LXCN
SPXV02.5TXCN
SPXV020.LXCN
SPXV020.TXCN
SPXV025.LXMCN
SPXV025.TXMCN
SPXV03.5LXCN
SPXV03.5TXCN
SPXV030.LXMCN
SPXV030.TXMCN
SPXV032.LXMCN
SPXV032.TXMCN
SPXV04.5LXCN
SPXV04.5TXCN
SPXV2.25LXCN
SPXV2.25TXCN