



## Product/Process Change Notice - PCN 12\_0236 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

**PCN Title:** AD5425 Datasheet Correction

**Publication Date:** 28-Sep-2012

**Effectivity Date:** 28-Sep-2012 *(the earliest date that a customer could expect to receive changed material)*

### Revision Description:

Initial Release

### Description Of Change

DAC Update Rate change from 9.5MSPS to 2.47MSPS

### Reason For Change

Update datasheet to accurately reflect correct DAC Update Rate.

### Impact of the change (positive or negative) on fit, form, function & reliability

There has been no change to the device silicon. there will be no impact on fit, form, function or reliability.

### Summary of Supporting Information

The AD5425 Datasheet Rev C reflects the correct DAC Update Rate .

**Supporting Documents** None

**For questions on this PCN, send email to the regional contacts below or contact your local ADI sales representative**

**Americas:** PCN\_Americas@analog.com

**Europe:** PCN\_Europe@analog.com

**Japan:** PCN\_Japan@analog.com

**Rest of Asia:** PCN\_ROA@analog.com

**Appendix A - Affected ADI Models**

**Added Parts On This Revision - Product Family / Model Number (6)**

AD5425 / AD5425YRM	AD5425 / AD5425YRM-REEL	AD5425 / AD5425YRM-REEL7	AD5425 / AD5425YRMZ	AD5425 / AD5425YRMZ-REEL
AD5425 / AD5425YRMZ-REEL7				

**Appendix B - Revision History**

<b>Rev</b>	<b>Publish Date</b>	<b>Effectivity Date</b>	<b>Rev Description</b>
Rev. -	28-Sep-2012	28-Sep-2012	Initial Release

Analog Devices, Inc.

DocId:2112 Parent DocId:None Layout Rev:7