

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type Description	Customer part no.
SBU	PG	PGU	Type			
02	007	060	0000002247	4747.0000	4747 MINIBLOC with inlet	4747
02	007	060	0000002248	4748.0300	4748 MINIBLOC with cable	4748

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
4747.0000	4748.0300	4748.1300	4748.2300	4748.3300


2 Type of change

Modification of fixing hole.

3 Detailed description of change

On bottom side, new shape of fixing hole for more hole spacing.


Old: circular fixing holes



New: elongated fixing holes



New spacing between fixing holes 134mm – 135mm



4 Reason of change

With the elongated shape of fixing holes, tolerance of hole spacing, 134mm to 135mm, can be met.

5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 10/2014 and last.

6 Impact of change and recommended action

Form: New elongated fixing holes
Fit: Hole spacing 134mm to 135mm
Function: N/A
Production Site: N/A
Product Label: N/A

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet 4747		
Data sheet 4748		

4747 / 4748 Minibloc					0118.2181	
creation date	created by	release date	released by	notification no.	revision	page
2013-07-23	hotzar	2013-11-11	hermanur	25283	-	1 of 1