



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3	K	L
ELM 3-030	K	L
ELM 3-040	K	L
ELM 3-045	K	L
ELM 3-050	K	L
ELM 3-055	K	L
ELM 3-060	K	L
ELM 3-065	K	L
ELM 3-070	K	L
ELM 3-075	K	L
ELM 3-080	K	L
ELM 3-085	K	L
ELM 3-090	K	L
ELM 3-095	K	L
ELM 3-1.000	K	L
ELM 3-1.015	K	L
ELM 3-1.020	K	L
ELM 3-1.025	K	L
ELM 3-1.030	K	L
ELM 3-1.035	K	L
ELM 3-1.040	K	L
ELM 3-1.045	K	L
ELM 3-1.050	K	L
ELM 3-1.055	K	L
ELM 3-1.005	K	L
ELM 3-1.010	K	L
ELM 3-1.060	K	L
ELM 3-1.065	K	L
ELM 3-1.070	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-1.075	K	L
ELM 3-1.080	K	L
ELM 3-1.085	K	L
ELM 3-1.090	K	L
ELM 3-1.095	K	L
ELM 3-1.100	K	L
ELM 3-1.105	K	L
ELM 3-1.110	K	L
ELM 3-1.115	K	L
ELM 3-1.120	K	L
ELM 3-1.125	K	L
ELM 3-1.130	K	L
ELM 3-1.135	K	L
ELM 3-1.140	K	L
ELM 3-1.145	K	L
ELM 3-1.150	K	L
ELM 3-1.155	K	L
ELM 3-1.160	K	L
ELM 3-1.165	K	L
ELM 3-1.170	K	L
ELM 3-1.175	K	L
ELM 3-1.180	K	L
ELM 3-1.185	K	L
ELM 3-1.190	K	L
ELM 3-1.195	K	L
ELM 3-1.200	K	L
ELM 3-1.205	K	L
ELM 3-1.210	K	L
ELM 3-1.215	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-1.220	K	L
ELM 3-1.225	K	L
ELM 3-1.230	K	L
ELM 3-1.235	K	L
ELM 3-1.240	K	L
ELM 3-1.245	K	L
ELM 3-1.250	K	L
ELM 3-1.500	K	L
ELM 3-100	K	L
ELM 3-105	K	L
ELM 3-10MM	K	L
ELM 3-11MM	K	L
ELM 3-110	K	L
ELM 3-115	K	L
ELM 3-120	K	L
ELM 3-125	K	L
ELM 3-130	K	L
ELM 3-135	K	L
ELM 3-12MM	K	L
ELM 3-13MM	K	L
ELM 3-140	K	L
ELM 3-145	K	L
ELM 3-14MM	K	L
ELM 3-150	K	L
ELM 3-155	K	L
ELM 3-15MM	K	L
ELM 3-160	K	L
ELM 3-165	K	L
ELM 3-16MM	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-170	K	L
ELM 3-175	K	L
ELM 3-17MM	K	L
ELM 3-180	K	L
ELM 3-185	K	L
ELM 3-187	K	L
ELM 3-18MM	K	L
ELM 3-190	K	L
ELM 3-195	K	L
ELM 3-200	K	L
ELM 3-205	K	L
ELM 3-20MM	K	L
ELM 3-210	K	L
ELM 3-215	K	L
ELM 3-21MM	K	L
ELM 3-220	K	L
ELM 3-225	K	L
ELM 3-22MM	K	L
ELM 3-230	K	L
ELM 3-235	K	L
ELM 3-23MM	K	L
ELM 3-240	K	L
ELM 3-245	K	L
ELM 3-24MM	K	L
ELM 3-250	K	L
ELM 3-255	K	L
ELM 3-25MM	K	L
ELM 3-260	K	L
ELM 3-265	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-270	K	L
ELM 3-275	K	L
ELM 3-27MM	K	L
ELM 3-280	K	L
ELM 3-285	K	L
ELM 3-28MM	K	L
ELM 3-290	K	L
ELM 3-295	K	L
ELM 3-29MM	K	L
ELM 3-2MM	K	L
ELM 3-300	K	L
ELM 3-305	K	L
ELM 3-310	K	L
ELM 3-30MM	K	L
ELM 3-315	K	L
ELM 3-320	K	L
ELM 3-325	K	L
ELM 3-330	K	L
ELM 3-335	K	L
ELM 3-340	K	L
ELM 3-345	K	L
ELM 3-350	K	L
ELM 3-355	K	L
ELM 3-360	K	L
ELM 3-365	K	L
ELM 3-370	K	L
ELM 3-375	K	L
ELM 3-380	K	L
ELM 3-385	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-390	K	L
ELM 3-395	K	L
ELM 3-3MM	K	L
ELM 3-400	K	L
ELM 3-405	K	L
ELM 3-410	K	L
ELM 3-415	K	L
ELM 3-420	K	L
ELM 3-425	K	L
ELM 3-430	K	L
ELM 3-435	K	L
ELM 3-440	K	L
ELM 3-445	K	L
ELM 3-450	K	L
ELM 3-455	K	L
ELM 3-460	K	L
ELM 3-465	K	L
ELM 3-470	K	L
ELM 3-475	K	L
ELM 3-480	K	L
ELM 3-485	K	L
ELM 3-490	K	L
ELM 3-495	K	L
ELM 3-4MM	K	L
ELM 3-500	K	L
ELM 3-505	K	L
ELM 3-510	K	L
ELM 3-515	K	L
ELM 3-520	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-525	K	L
ELM 3-530	K	L
ELM 3-535	K	L
ELM 3-540	K	L
ELM 3-545	K	L
ELM 3-550	K	L
ELM 3-555	K	L
ELM 3-560	K	L
ELM 3-565	K	L
ELM 3-570	K	L
ELM 3-575	K	L
ELM 3-580	K	L
ELM 3-585	K	L
ELM 3-590	K	L
ELM 3-595	K	L
ELM 3-5MM	K	L
ELM 3-600	K	L
ELM 3-605	K	L
ELM 3-610	K	L
ELM 3-615	K	L
ELM 3-620	K	L
ELM 3-625	K	L
ELM 3-630	K	L
ELM 3-635	K	L
ELM 3-640	K	L
ELM 3-645	K	L
ELM 3-650	K	L
ELM 3-655	K	L
ELM 3-660	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-670	K	L
ELM 3-675	K	L
ELM 3-680	K	L
ELM 3-685	K	L
ELM 3-690	K	L
ELM 3-695	K	L
ELM 3-6MM	K	L
ELM 3-700	K	L
ELM 3-705	K	L
ELM 3-710	K	L
ELM 3-715	K	L
ELM 3-720	K	L
ELM 3-725	K	L
ELM 3-730	K	L
ELM 3-735	K	L
ELM 3-740	K	L
ELM 3-745	K	L
ELM 3-750	K	L
ELM 3-780	K	L
ELM 3-785	K	L
ELM 3-790	K	L
ELM 3-795	K	L
ELM 3-7MM	K	L
ELM 3-800	K	L
ELM 3-805	K	L
ELM 3-810	K	L
ELM 3-815	K	L
ELM 3-820	K	L
ELM 3-825	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122





PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	Old Rev.	New Rev.
ELM 3-830	K	L
ELM 3-835	K	L
ELM 3-840	K	L
ELM 3-845	K	L
ELM 3-850	K	L
ELM 3-855	K	L
ELM 3-860	K	L
ELM 3-865	K	L
ELM 3-870	K	L
ELM 3-875	K	L
ELM 3-880	K	L
ELM 3-885	K	L
ELM 3-890	K	L
ELM 3-895	K	L
ELM 3-8MM	K	L
ELM 3-900	K	L
ELM 3-905	K	L
ELM 3-910	K	L
ELM 3-915	K	L
ELM 3-920	K	L
ELM 3-925	K	L
ELM 3-930	K	L
ELM 3-935	K	L
ELM 3-940	K	L
ELM 3-945	K	L
ELM 3-950	K	L
ELM 3-955	K	L
ELM 3-960	K	L
ELM 3-965	K	L

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



**PRODUCT CHANGE NOTIFICATION**

PCN No: PCN-1074

Issue Date: 12/10/2024

Parts Affected	ELM 3-970	Old Rev.	K	New Rev.	L
	ELM 3-975		K		L
	ELM 3-980		K		L
	ELM 3-985		K		L
	ELM 3-990		K		L
	ELM 3-995		K		L
	ELM 3-9MM		K		L

**Change Will Affect:**

This change will affect the product form.

**Description of Change:**

The center hole dimension has been changed from 0.025in to 0.035in.

**Effective Date of Change:** December 10, 2024

**Reason for Change:** For manufacturing purposes.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122