



PRODUCT CHANGE NOTIFICATION

MAGNETICS



Bourns® Model SM51589PEL LAN Transformer

Change in Source of Supply for Glue

Riverside, California - December 4, 2023 – To enhance continuity of supply and provide maximum flexibility to customers, effective immediately, Bourns will change its glue material supplier for the [Model SM51589PEL LAN Transformer](#). The new supplier has been qualified and is included in the Bourns Authorized Vendor List. The affected part number is provided below.

Affected Part Number

SM51589PEL

The form, fit, function, quality, reliability and country of origin of the affected transformer will not change. The change of supplier will not change the data sheet specifications for the affected model. The production lead time of the transformer will remain the same. Traceability will be maintained through lot code and date code.

Samples built using the glue from the new supplier are available upon request. Bourns recommends that customers test the affected part number in their specific applications for verification of satisfactory performance.

Implementation dates are as follows:

First date code using the above changes: **2348**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC23146