

Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

# **Product Change Notice**

PCN#: EE-PCN23027 December 21, 2023

#### **CLASSIFICATION OF CHANGE:**

Material Change.

### **DESCRIPTION OF CHANGE:**

Replace top surface Kapton tape with white label tape.

## **REASON FOR CHANGE:**

The white label tape is thicker and flatter compared to the Kapton tape and therefore improves pick and place capability.

### **EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

There is no change to form or fit. Mechanically, the white label tape improves pick and place function. There is a change in appearance to the top of the inductors.

| Part                                 | Kapton tape (current) | White label tape (new) |
|--------------------------------------|-----------------------|------------------------|
| TL1011V1-Rxxx-RI & TL1011V1-Rxxx-RV  |                       |                        |
| FP1010V14-Rxxx-R & FP1010V14-Rxxx-RI |                       |                        |

#### **PARTS FAMILIES AFFECTED:**

See following page for part number list.

TIME SCHEDULE:

Effective Date: Jan 20, 2024

**ISSUED BY:** 

Product Manager: Steve Subiry

### **CONTACT INFORMATION:**

For questions or comments, please contact your local Eaton sales representative.

# PARTS FAMILIES AFFECTED:

| Material         | Material         | Material          |
|------------------|------------------|-------------------|
| TL1011V1-R070-RI | TL1011V1-R070-RV | FP1010V14-R070-R  |
| TL1011V1-R080-RI | TL1011V1-R080-RV | FP1010V14-R090-R  |
| TL1011V1-R100-RI | TL1011V1-R100-RV | FP1010V14-R100-R  |
| TL1011V1-R110-RI | TL1011V1-R110-RV | FP1010V14-R070-RI |
| TL1011V1-R120-RI | TL1011V1-R120-RV | FP1010V14-R090-RI |
| TL1011V1-R150-RI | TL1011V1-R150-RV | FP1010V14-R100-RI |
| TL1011V1-R170-RI | TL1011V1-R170-RV |                   |