

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU Type				
04	017	004	0000008034	See list below	Protection	T9-611 ...
04	017	004	0000008035	See list below	Protection	T9-311/211 ...
04	017	004	0000008036	See list below	Protection	T9-711 ...

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected						
4404.0001	4404.0002	4404.0003	4404.0004	4404.0005	4404.0006	4404.0007
4404.0008	4404.0009	4404.0010	4404.0018	4404.0019	4404.0020	4404.0021
4404.0022	4404.0023	4404.0024	4404.0025	4404.0026	4404.0027	4404.0028
4404.0029	4404.0030	4404.0031	4404.0032	4404.0033	4404.0034	4404.0035
4404.0036	4404.0037	4404.0038	4404.0039	4404.0040	4404.0041	4404.0049
4404.0057	4404.0059	4404.0060	4404.0061	4404.0062	4404.0063	4404.0064
4404.0065	4404.0066	4404.0067	4404.0068	4404.0069	4404.0070	4404.0071
4404.0072	4404.0073	4404.0074	4404.0075	4404.0076	4404.0077	4404.0078
4404.0074	4404.0075	4404.0083	4404.0084	4404.0033	4404.0034	4404.0035
4404.0079	4404.0080	4404.0081	4404.0082	4404.0083	4404.0084	4404.0085
4404.0086	4404.0087	4404.0088	4404.0089	4404.0090	4404.0091	4404.0092
4404.0093	4404.0094	4404.0095				

2 Type of change

Production site changed to India

3 Detailed description of change

Manufacturing facility in India

4 Reason of change

Strategic decision

5 Released date

November 2012

Please see the productlabel

6 Impact of change and recommended action

Form: -
Fit: -
Function: Without CCC approval until first quarter 2013
Production Site: Made in India

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Link to Web Datasheet		http://www.schurter.com/var/schurter/storage/ilcatalogue/files/document/datasheet/en/pdf/typ_T9-611.pdf

T9					0118.2120	
creation date	created by	release date	released by	notification no.	revision	page
2012-08-20	dsc	2012-10-31	cvo	23827	-	1 of 1