

1 Products affected

Product hierarchy no. *			archy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PO	G	PGU	Туре				
03 0)70	011	0000003424	See list below	Switches	PSE EX	
*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)							

List of part numbers affected						
1241.2415.1	1241.2615					
1241.2415.3						
1241.2415.4						
1241.2415.5						
1241.2415.7						
1241.2415.8						

2 Type of change

New and extended approval according to ATEX and IECEx.


3 Detailed description of change

Approval up to now:

🖾 II 2 G Ex ib IIB T4

TÜV 08 ATEX 554671 X

(EC-Type Examination Certificate)



(example of PSE M16 EX)

	0118.2193					
creation date	created by	release date	released by	notification no.	revision	page
2013-11-18	halterma	2014-03-10	halterma	25236	_	1 of 2




New approval:

II 2 G Ex ib IIC T6...T5 Gb
II 2 D Ex ib IIIC T85°C...100°C Db

SEV 13 ATEX 0170 IECEx SEV 13.0011 (EC-Type Examination Certificate) (IECEx Certificate of Conformity)

SEV 12 ATEX 4119

(Anerkennung der Qualitätssicherung Produktion)



(example of PSE M16 EX)

4 Reason of change

- Extended approval
- New approval according to IECEx
- New EC-Type Examination Certificate
- New approval of production site

5 Release date

Rolled-out of the change in ww 11/2014.

6 Impact of change and recommended action

Form:	New approval
Fit:	N/A
Function:	N/A
Production Site:	New approval
Product Label:	Modified tag

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Datasheet		PSE EX

PSE EX						0118.2193	
creation date	created by	release date	released by	notification no.	revision	page	
2013-11-18	halterma	2014-03-10	halterma	25236	_	2 of 2	