

1 Products affected

Product hierarchy no. *				SBU	Part. no.	Configuration code
SBU	PG	PUG	Type			
80	081	002	0000006502	EMC	DFKH-14-0001	DFKH2-14-0.6-11/A
80	081	002	0000006502	EMC	DFKH-14-0002	DFKH2-14-1.0-4/A
80	081	002	0000006502	EMC	DFKH-14-0003	DFKH2-14-2.0-1/A


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Terminal pins changed

3 Detailed description of change

- Rectangular pins substituted with round pins



4 Reason of change

- Standardization of choke cases
- Optimize assembly process

5 Release date

The change will be rolled-out starting wk 24/2021 (Date code 2124 or higher on label) and lasts approx. 6 months.

6 Action

Form	No	-
Fit	Yes	Pin diameter and shape
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					PCN DFKH-14 round pins		
owner	creation date	release date	released by	change order no	rev	page	D10-045-928
segatro	26.05.2020	03.02.2021	blumhe	2019984	A	1 of 1	