

Attn.: \_\_\_\_\_

**HIROSE ELECTRIC CO., LTD.**

5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

**Notice of the Addition of a Production Location for Products Manufactured at Our Malaysia Factory and Request for Your Acknowledgement**

We sincerely appreciate your continued patronage.

Hirose Electric would like to inform you that regarding certain items being manufactured at our Malaysia Factory, we will add our Indonesia Factory in our manufacturing site.

This letter is intended to provide you with previous notice. Thank you for your understanding.

1. Applicable products

Please refer to the list of applicable products in the attached separate sheet.

2. Details

The applicable products will in future be manufactured in either the Malaysia factory or the Indonesia factory.

Indonesian production will be supervised by the Malaysia factory, which will monitor the whole process, including giving instructions from production to shipment.

3. Change implementation timescale

Products manufactured from January 2016.

4. Acknowledgement

We appreciate it if you could notify our sales representative with your acknowledgment by the end of October, 2015.

If we do not receive your reply by the above date, please be aware that products described in this documentation will be delivered subject to the production changes described.

If further clarification is needed, please ask our sales representative.

## List of products applicable to additional production location

No.	CL Code	Product Name	Production Location		Start Date for Additional Production	Supervising Factory
			Current	Added		
1	570-0300-6 71	FX10B-200P/20-SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
2	570-0301-9 71	FX10B-200S/20-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
3	573-0548-0 21	FX11A-80P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
4	573-0004-2 71	FX11LA-100P/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
5	573-0004-2 91	FX11LA-100P/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
6	573-0004-2 92	FX11LA-100P/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
7	573-0104-7 71	FX11LA-100S/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
8	573-0104-7 91	FX11LA-100S/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
9	573-0104-7 92	FX11LA-100S/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
10	573-0044-7 00	FX11LA-116P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
11	573-0044-7 21	FX11LA-116P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
12	573-0044-7 22	FX11LA-116P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
13	573-0144-1 00	FX11LA-116S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
14	573-0144-1 21	FX11LA-116S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
15	573-0144-1 22	FX11LA-116S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
16	573-0005-5 71	FX11LA-120P/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
17	573-0005-5 91	FX11LA-120P/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
18	573-0005-5 92	FX11LA-120P/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
19	573-0105-0 71	FX11LA-120S/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
20	573-0105-0 91	FX11LA-120S/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
21	573-0105-0 92	FX11LA-120S/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
22	573-0045-0 00	FX11LA-140P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
23	573-0045-0 21	FX11LA-140P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
24	573-0045-0 22	FX11LA-140P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
25	573-0145-4 00	FX11LA-140S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
26	573-0145-4 21	FX11LA-140S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
27	573-0145-4 22	FX11LA-140S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
28	573-0102-1 71	FX11LA-60S/6-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
29	573-0102-1 91	FX11LA-60S/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
30	573-0102-1 92	FX11LA-60S/6-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
31	573-0102-1 98	FX11LA-60S/6-SV(98)	Malaysia	Indonesia	Jan-2016	Malaysia
32	573-0042-1 00	FX11LA-68P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
33	573-0042-1 21	FX11LA-68P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
34	573-0042-1 22	FX11LA-68P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
35	573-0142-6 00	FX11LA-68S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
36	573-0142-6 21	FX11LA-68S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
37	573-0142-6 22	FX11LA-68S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
38	573-0003-0 71	FX11LA-80P/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
39	573-0003-0 91	FX11LA-80P/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
40	573-0003-0 92	FX11LA-80P/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
41	573-0103-4 71	FX11LA-80S/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
42	573-0103-4 91	FX11LA-80S/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
43	573-0103-4 92	FX11LA-80S/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
44	573-0043-4 00	FX11LA-92P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
45	573-0043-4 21	FX11LA-92P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
46	573-0043-4 22	FX11LA-92P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
47	573-0143-9 00	FX11LA-92S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
48	573-0143-9 21	FX11LA-92S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
49	573-0143-9 22	FX11LA-92S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
50	573-0014-6 71	FX11LB-100P/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
51	573-0014-6 91	FX11LB-100P/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
52	573-0014-6 92	FX11LB-100P/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
53	573-0114-0 71	FX11LB-100S/10-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
54	573-0114-0 91	FX11LB-100S/10-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
55	573-0114-0 92	FX11LB-100S/10-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
56	573-0054-0 00	FX11LB-116P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
57	573-0054-0 21	FX11LB-116P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
58	573-0054-0 22	FX11LB-116P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
59	573-0154-5 00	FX11LB-116S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
60	573-0154-5 21	FX11LB-116S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
61	573-0154-5 22	FX11LB-116S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
62	573-0015-9 71	FX11LB-120P/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
63	573-0015-9 91	FX11LB-120P/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional Production	Supervising Factory
			Current	Added		
64	573-0015-9 92	FX11LB-120P/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
65	573-0115-3 71	FX11LB-120S/12-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
66	573-0115-3 91	FX11LB-120S/12-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
67	573-0115-3 92	FX11LB-120S/12-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
68	573-0055-3 00	FX11LB-140P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
69	573-0055-3 21	FX11LB-140P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
70	573-0055-3 22	FX11LB-140P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
71	573-0155-8 00	FX11LB-140S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
72	573-0155-8 21	FX11LB-140S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
73	573-0155-8 22	FX11LB-140S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
74	573-0112-5 71	FX11LB-60S/6-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
75	573-0112-5 91	FX11LB-60S/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
76	573-0112-5 92	FX11LB-60S/6-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
77	573-0112-5 97	FX11LB-60S/6-SV(97)	Malaysia	Indonesia	Jan-2016	Malaysia
78	573-0052-5 00	FX11LB-68P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
79	573-0052-5 21	FX11LB-68P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
80	573-0052-5 22	FX11LB-68P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
81	573-0152-0 00	FX11LB-68S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
82	573-0152-0 21	FX11LB-68S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
83	573-0152-0 22	FX11LB-68S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
84	573-0056-6 91	FX11LB-72P/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
85	573-0157-3 91	FX11LB-72S/6-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
86	573-0013-3 71	FX11LB-80P/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
87	573-0013-3 91	FX11LB-80P/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
88	573-0013-3 92	FX11LB-80P/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
89	573-0113-8 71	FX11LB-80S/8-SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
90	573-0113-8 91	FX11LB-80S/8-SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
91	573-0113-8 92	FX11LB-80S/8-SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
92	573-0053-8 00	FX11LB-92P-SV	Malaysia	Indonesia	Jan-2016	Malaysia
93	573-0053-8 21	FX11LB-92P-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
94	573-0053-8 22	FX11LB-92P-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
95	573-0153-2 00	FX11LB-92S-SV	Malaysia	Indonesia	Jan-2016	Malaysia
96	573-0153-2 21	FX11LB-92S-SV(21)	Malaysia	Indonesia	Jan-2016	Malaysia
97	573-0153-2 22	FX11LB-92S-SV(22)	Malaysia	Indonesia	Jan-2016	Malaysia
98	576-0008-2 71	FX6-100P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
99	576-0008-2 91	FX6-100P-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
100	576-0028-0 71	FX6-100P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
101	576-0028-0 91	FX6-100P-0.8SV1(91)	Malaysia	Indonesia	Jan-2016	Malaysia
102	576-0028-0 92	FX6-100P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
103	576-0048-7 71	FX6-100P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
104	576-0048-7 91	FX6-100P-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
105	576-0048-7 93	FX6-100P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
106	576-0108-7 71	FX6-100S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
107	576-0108-7 91	FX6-100S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
108	576-0108-7 93	FX6-100S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
109	576-0128-4 71	FX6-100S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
110	576-0128-4 91	FX6-100S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
111	576-0128-4 92	FX6-100S-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
112	576-0128-4 93	FX6-100S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
113	576-0049-0 92	FX6-12P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
114	576-0001-3 71	FX6-20P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
115	576-0001-3 92	FX6-20P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
116	576-0001-3 93	FX6-20P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
117	576-0021-0 71	FX6-20P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
118	576-0021-0 92	FX6-20P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
119	576-0021-0 93	FX6-20P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
120	576-0041-8 71	FX6-20P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
121	576-0041-8 92	FX6-20P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
122	576-0041-8 93	FX6-20P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
123	576-0101-8 71	FX6-20S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
124	576-0101-8 91	FX6-20S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
125	576-0101-8 92	FX6-20S-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
126	576-0101-8 93	FX6-20S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
127	576-0121-5 71	FX6-20S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
128	576-0121-5 93	FX6-20S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional Production	Supervising Factory
			Current	Added		
129	576-0003-9 71	FX6-40P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
130	576-0003-9 92	FX6-40P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
131	576-0023-6 71	FX6-40P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
132	576-0023-6 92	FX6-40P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
133	576-0023-6 93	FX6-40P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
134	576-0043-3 71	FX6-40P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
135	576-0043-3 91	FX6-40P-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
136	576-0043-3 92	FX6-40P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
137	576-0043-3 93	FX6-40P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
138	576-0103-3 71	FX6-40S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
139	576-0103-3 93	FX6-40S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
140	576-0103-3 97	FX6-40S-0.8SV(97)	Malaysia	Indonesia	Jan-2016	Malaysia
141	576-0123-0 71	FX6-40S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
142	576-0123-0 91	FX6-40S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
143	576-0123-0 93	FX6-40S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
144	576-0004-1 71	FX6-50P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
145	576-0004-1 92	FX6-50P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
146	576-0004-1 93	FX6-50P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
147	576-0024-9 71	FX6-50P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
148	576-0024-9 92	FX6-50P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
149	576-0044-6 71	FX6-50P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
150	576-0044-6 92	FX6-50P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
151	576-0044-6 93	FX6-50P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
152	576-0104-6 71	FX6-50S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
153	576-0104-6 91	FX6-50S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
154	576-0104-6 93	FX6-50S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
155	576-0124-3 71	FX6-50S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
156	576-0124-3 93	FX6-50S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
157	576-0005-4 71	FX6-60P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
158	576-0005-4 92	FX6-60P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
159	576-0005-4 93	FX6-60P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
160	576-0025-1 71	FX6-60P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
161	576-0025-1 92	FX6-60P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
162	576-0025-1 93	FX6-60P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
163	576-0045-9 71	FX6-60P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
164	576-0045-9 92	FX6-60P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
165	576-0105-9 71	FX6-60S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
166	576-0105-9 93	FX6-60S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
167	576-0125-6 71	FX6-60S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
168	576-0125-6 91	FX6-60S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
169	576-0125-6 93	FX6-60S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
170	576-0007-0 71	FX6-80P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
171	576-0007-0 93	FX6-80P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
172	576-0027-7 71	FX6-80P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
173	576-0027-7 92	FX6-80P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
174	576-0027-7 93	FX6-80P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
175	576-0047-4 71	FX6-80P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
176	576-0047-4 92	FX6-80P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
177	576-0047-4 93	FX6-80P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
178	576-0107-4 71	FX6-80S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
179	576-0107-4 91	FX6-80S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
180	576-0107-4 93	FX6-80S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
181	576-0127-1 71	FX6-80S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
182	576-0127-1 91	FX6-80S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
183	576-0127-1 93	FX6-80S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
184	576-0208-1 71	FX6A-100P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
185	576-0228-9 71	FX6A-100P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
186	576-0248-6 71	FX6A-100P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
187	576-0308-6 71	FX6A-100S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
188	576-0308-6 91	FX6A-100S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
189	576-0328-3 71	FX6A-100S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
190	576-0328-3 91	FX6A-100S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
191	576-0201-2 71	FX6A-20P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
192	576-0201-2 92	FX6A-20P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
193	576-0201-2 93	FX6A-20P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional Production	Supervising Factory
			Current	Added		
194	576-0221-0 71	FX6A-20P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
195	576-0221-0 92	FX6A-20P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
196	576-0221-0 93	FX6A-20P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
197	576-0241-7 71	FX6A-20P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
198	576-0241-7 92	FX6A-20P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
199	576-0241-7 93	FX6A-20P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
200	576-0301-7 71	FX6A-20S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
201	576-0301-7 93	FX6A-20S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
202	576-0321-4 71	FX6A-20S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
203	576-0321-4 93	FX6A-20S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
204	576-0242-0 93	FX6A-30P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
205	576-0322-7 93	FX6A-30S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
206	576-0203-8 71	FX6A-40P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
207	576-0203-8 92	FX6A-40P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
208	576-0223-5 71	FX6A-40P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
209	576-0223-5 92	FX6A-40P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
210	576-0223-5 93	FX6A-40P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
211	576-0243-2 71	FX6A-40P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
212	576-0243-2 92	FX6A-40P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
213	576-0243-2 93	FX6A-40P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
214	576-0303-2 71	FX6A-40S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
215	576-0303-2 91	FX6A-40S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
216	576-0303-2 93	FX6A-40S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
217	576-0323-0 71	FX6A-40S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
218	576-0323-0 93	FX6A-40S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
219	576-0204-0 71	FX6A-50P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
220	576-0204-0 92	FX6A-50P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
221	576-0204-0 93	FX6A-50P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
222	576-0224-8 71	FX6A-50P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
223	576-0224-8 92	FX6A-50P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
224	576-0224-8 93	FX6A-50P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
225	576-0244-5 71	FX6A-50P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
226	576-0244-5 92	FX6A-50P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
227	576-0304-5 71	FX6A-50S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
228	576-0304-5 93	FX6A-50S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
229	576-0324-2 71	FX6A-50S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
230	576-0324-2 91	FX6A-50S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
231	576-0324-2 93	FX6A-50S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
232	576-0205-3 71	FX6A-60P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
233	576-0205-3 92	FX6A-60P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
234	576-0225-0 71	FX6A-60P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
235	576-0225-0 92	FX6A-60P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
236	576-0225-0 93	FX6A-60P-0.8SV1(93)	Malaysia	Indonesia	Jan-2016	Malaysia
237	576-0245-8 71	FX6A-60P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
238	576-0245-8 92	FX6A-60P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
239	576-0245-8 93	FX6A-60P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
240	576-0305-8 71	FX6A-60S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
241	576-0305-8 93	FX6A-60S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
242	576-0325-5 71	FX6A-60S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
243	576-0325-5 93	FX6A-60S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
244	576-0207-9 71	FX6A-80P-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
245	576-0207-9 92	FX6A-80P-0.8SV(92)	Malaysia	Indonesia	Jan-2016	Malaysia
246	576-0207-9 93	FX6A-80P-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
247	576-0227-6 71	FX6A-80P-0.8SV1(71)	Malaysia	Indonesia	Jan-2016	Malaysia
248	576-0227-6 92	FX6A-80P-0.8SV1(92)	Malaysia	Indonesia	Jan-2016	Malaysia
249	576-0247-3 71	FX6A-80P-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
250	576-0247-3 92	FX6A-80P-0.8SV2(92)	Malaysia	Indonesia	Jan-2016	Malaysia
251	576-0247-3 93	FX6A-80P-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
252	576-0307-3 71	FX6A-80S-0.8SV(71)	Malaysia	Indonesia	Jan-2016	Malaysia
253	576-0307-3 91	FX6A-80S-0.8SV(91)	Malaysia	Indonesia	Jan-2016	Malaysia
254	576-0307-3 93	FX6A-80S-0.8SV(93)	Malaysia	Indonesia	Jan-2016	Malaysia
255	576-0327-0 71	FX6A-80S-0.8SV2(71)	Malaysia	Indonesia	Jan-2016	Malaysia
256	576-0327-0 91	FX6A-80S-0.8SV2(91)	Malaysia	Indonesia	Jan-2016	Malaysia
257	576-0327-0 93	FX6A-80S-0.8SV2(93)	Malaysia	Indonesia	Jan-2016	Malaysia
258	578-0205-6 00	FX8-100S-SV	Malaysia	Indonesia	Apr-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional Production	Supervising Factory
			Current	Added		
259	578-0205-6 21	FX8-100S-SV(21)	Malaysia	Indonesia	Apr-2016	Malaysia
260	578-0201-5 00	FX8-60S-SV	Malaysia	Indonesia	Apr-2016	Malaysia
261	578-0201-5 21	FX8-60S-SV(21)	Malaysia	Indonesia	Apr-2016	Malaysia
262	578-0201-5 22	FX8-60S-SV(22)	Malaysia	Indonesia	Apr-2016	Malaysia
263	578-0203-0 00	FX8-80S-SV	Malaysia	Indonesia	Apr-2016	Malaysia
264	578-0203-0 21	FX8-80S-SV(21)	Malaysia	Indonesia	Apr-2016	Malaysia
265	578-0203-0 22	FX8-80S-SV(22)	Malaysia	Indonesia	Apr-2016	Malaysia
266	578-0203-0 88	FX8-80S-SV(88)	Malaysia	Indonesia	Apr-2016	Malaysia
267	578-0601-3 80	FX8C-60P-SV6(80)	Malaysia	Indonesia	Apr-2016	Malaysia
268	578-1003-7 00	FX8CS-140P-SV6	Malaysia	Indonesia	Apr-2016	Malaysia
269	578-1003-7 86	FX8CS-140P-SV6(86)	Malaysia	Indonesia	Apr-2016	Malaysia
270	578-1004-0 00	FX8CS-140S-SV5	Malaysia	Indonesia	Apr-2016	Malaysia
271	578-1004-0 84	FX8CS-140S-SV5(84)	Malaysia	Indonesia	Apr-2016	Malaysia
272	630-0011-8 00	HIF6-100D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
273	630-0011-8 02	HIF6-100D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
274	630-0011-8 05	HIF6-100D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
275	630-0001-4 00	HIF6-20D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
276	630-0002-7 00	HIF6-26D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
277	630-0003-0 00	HIF6-32D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
278	630-0004-2 00	HIF6-34D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
279	630-0004-2 02	HIF6-34D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
280	630-0005-5 00	HIF6-40D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
281	630-0006-8 00	HIF6-50D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
282	630-0006-8 02	HIF6-50D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
283	630-0006-8 05	HIF6-50D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
284	630-0007-0 00	HIF6-52D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
285	630-0008-3 00	HIF6-60D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
286	630-0008-3 05	HIF6-60D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
287	630-0009-6 00	HIF6-68D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
288	630-0009-6 02	HIF6-68D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
289	630-0010-5 00	HIF6-80D-1.27R	Malaysia	Indonesia	Apr-2016	Malaysia
290	630-0010-5 02	HIF6-80D-1.27R(02)	Malaysia	Indonesia	Apr-2016	Malaysia
291	630-0010-5 05	HIF6-80D-1.27R(05)	Malaysia	Indonesia	Apr-2016	Malaysia
292	222-2850-0 50	TM11R-5C-62(50)	Malaysia	Indonesia	May-2016	Malaysia
293	222-2148-6 50	TM11R-5C-66(50)	Malaysia	Indonesia	May-2016	Malaysia
294	222-1378-0 50	TM11R-5C-88(50)	Malaysia	Indonesia	May-2016	Malaysia
295	222-5133-5 50	TM11RX-5C-88(50)	Malaysia	Indonesia	May-2016	Malaysia
296	222-2981-8 00	TM24P-HR1-88(4)P1-TL	Malaysia	Indonesia	May-2016	Malaysia
297	222-2971-4 00	TM24P-HR1-88(4)P-TL	Malaysia	Indonesia	May-2016	Malaysia
298	222-2959-9 00	TM24P-HR1-88P-TL	Malaysia	Indonesia	May-2016	Malaysia
299	299-8006-0 00	TM24P-HR1-88P-TL-1	Malaysia	Indonesia	May-2016	Malaysia
300	222-2960-8 00	TM24P-HR2-88P-TL	Malaysia	Indonesia	May-2016	Malaysia
301	222-2972-7 00	TM24P-HR3-88(4)P-TL	Malaysia	Indonesia	May-2016	Malaysia
302	222-2961-0 00	TM24P-HR3-88P-TL	Malaysia	Indonesia	May-2016	Malaysia
303	222-2962-3 00	TM24P-HR-SHE1	Malaysia	Indonesia	May-2016	Malaysia
304	222-2963-6 00	TM24P-HR-SHE2	Malaysia	Indonesia	May-2016	Malaysia
305	222-1286-4 50	TM2RE-0602(50)	Malaysia	Indonesia	May-2016	Malaysia
306	222-1391-9 50	TM2RE-0604(50)	Malaysia	Indonesia	May-2016	Malaysia
307	222-1422-0 50	TM2RE-0606(50)	Malaysia	Indonesia	May-2016	Malaysia
308	222-0592-5 50	TM2RE-1204(50)	Malaysia	Indonesia	May-2016	Malaysia
309	222-0756-0 50	TM2RE-1208(50)	Malaysia	Indonesia	May-2016	Malaysia
310	222-0757-3 50	TM2RE-1212(50)	Malaysia	Indonesia	May-2016	Malaysia
311	222-0591-2 50	TM2RE-1806(50)	Malaysia	Indonesia	May-2016	Malaysia
312	222-0753-2 50	TM2RE-1812(50)	Malaysia	Indonesia	May-2016	Malaysia
313	222-0796-5 50	TM2RE-1818(50)	Malaysia	Indonesia	May-2016	Malaysia
314	222-0797-8 50	TM2RE-2408(50)	Malaysia	Indonesia	May-2016	Malaysia
315	222-0590-0 50	TM2RE-2416(50)	Malaysia	Indonesia	May-2016	Malaysia
316	222-0751-7 50	TM2RE-2424(50)	Malaysia	Indonesia	May-2016	Malaysia
317	222-1277-3 50	TM2REA-0602(50)	Malaysia	Indonesia	May-2016	Malaysia
318	222-1466-6 50	TM2REA-0604(50)	Malaysia	Indonesia	May-2016	Malaysia
319	222-1467-9 50	TM2REA-0606(50)	Malaysia	Indonesia	May-2016	Malaysia
320	222-0802-6 50	TM2REA-1204(50)	Malaysia	Indonesia	May-2016	Malaysia
321	222-0799-3 50	TM2REA-1208(50)	Malaysia	Indonesia	May-2016	Malaysia
322	222-3821-7 50	TM2REA-1210-64(50)	Malaysia	Indonesia	May-2016	Malaysia
323	222-0681-3 50	TM2REA-1212(50)	Malaysia	Indonesia	May-2016	Malaysia

No.	CL Code	Product Name	Production Location		Start Date for Additional Production	Supervising Factory
			Current	Added		
324	222-0801-3 50	TM2REA-1806(50)	Malaysia	Indonesia	May-2016	Malaysia
325	222-0798-0 50	TM2REA-1812(50)	Malaysia	Indonesia	May-2016	Malaysia
326	222-0737-6 50	TM2REA-1818(50)	Malaysia	Indonesia	May-2016	Malaysia
327	222-0800-0 50	TM2REA-2408(50)	Malaysia	Indonesia	May-2016	Malaysia
328	222-0749-5 50	TM2REA-2416(50)	Malaysia	Indonesia	May-2016	Malaysia
329	222-0750-4 50	TM2REA-2424(50)	Malaysia	Indonesia	May-2016	Malaysia
330	222-5018-7 50	TM2REAX-1204(50)	Malaysia	Indonesia	May-2016	Malaysia
331	222-5024-0 50	TM2REAX-2408(50)	Malaysia	Indonesia	May-2016	Malaysia
332	222-5025-2 65	TM2REAX-2416(65)	Malaysia	Indonesia	May-2016	Malaysia
333	222-1012-9 50	TM3RA-88(50)	Malaysia	Indonesia	May-2016	Malaysia
334	222-1012-9 55	TM3RA-88(55)	Malaysia	Indonesia	May-2016	Malaysia
335	222-1012-9 58	TM3RA-88(58)	Malaysia	Indonesia	May-2016	Malaysia
336	222-5034-3 50	TM3RAX-88(50)	Malaysia	Indonesia	May-2016	Malaysia
337	222-5047-5 50	TM5RBX-66-2.5DS(50)	Malaysia	Indonesia	May-2016	Malaysia
338	222-1513-4 50	TM5RC-1212(50)	Malaysia	Indonesia	May-2016	Malaysia
339	222-1513-4 51	TM5RC-1212(51)	Malaysia	Indonesia	May-2016	Malaysia
340	222-2578-5 50	TM5RC-1212-1.2(50)	Malaysia	Indonesia	May-2016	Malaysia
341	222-0270-9 50	TM5RC-44(50)	Malaysia	Indonesia	May-2016	Malaysia
342	222-0338-0 50	TM5RC-64(50)	Malaysia	Indonesia	May-2016	Malaysia
343	222-0337-8 50	TM5RC-66(50)	Malaysia	Indonesia	May-2016	Malaysia
344	222-0339-3 50	TM5RC-88(50)	Malaysia	Indonesia	May-2016	Malaysia
345	222-5136-3 20	TM5RE3VX-1212(20)	Malaysia	Indonesia	May-2016	Malaysia
346	222-1242-9 71	TM5RF1-44(71)	Malaysia	Indonesia	May-2016	Malaysia
347	222-5002-7 50	TM5RFX-44(50)	Malaysia	Indonesia	May-2016	Malaysia
348	222-1459-0 50	TM5RJ2-44(50)	Malaysia	Indonesia	May-2016	Malaysia
349	222-1486-3 50	TM5RJ2-62(50)	Malaysia	Indonesia	May-2016	Malaysia
350	222-1486-3 90	TM5RJ2-62(90)	Malaysia	Indonesia	May-2016	Malaysia
351	222-1460-0 50	TM5RJ2-64(50)	Malaysia	Indonesia	May-2016	Malaysia
352	222-1460-0 52	TM5RJ2-64(52)	Malaysia	Indonesia	May-2016	Malaysia
353	222-1461-2 50	TM5RJ2-66(50)	Malaysia	Indonesia	May-2016	Malaysia
354	222-1461-2 52	TM5RJ2-66(52)	Malaysia	Indonesia	May-2016	Malaysia
355	222-1461-2 53	TM5RJ2-66(53)	Malaysia	Indonesia	May-2016	Malaysia
356	222-1462-5 50	TM5RJ2-88(50)	Malaysia	Indonesia	May-2016	Malaysia
357	222-5081-3 50	TM5RJ2X-66(50)	Malaysia	Indonesia	May-2016	Malaysia
358	222-5081-3 53	TM5RJ2X-66(53)	Malaysia	Indonesia	May-2016	Malaysia
359	222-5082-6 50	TM5RJ2X-88(50)	Malaysia	Indonesia	May-2016	Malaysia
360	222-1363-3 50	TM5RJ3-44(50)	Malaysia	Indonesia	May-2016	Malaysia
361	222-1487-6 50	TM5RJ3-62(50)	Malaysia	Indonesia	May-2016	Malaysia
362	222-1463-8 50	TM5RJ3-64(50)	Malaysia	Indonesia	May-2016	Malaysia
363	222-1464-0 50	TM5RJ3-66(50)	Malaysia	Indonesia	May-2016	Malaysia
364	222-1464-0 51	TM5RJ3-66(51)	Malaysia	Indonesia	May-2016	Malaysia
365	222-1465-3 50	TM5RJ3-88(50)	Malaysia	Indonesia	May-2016	Malaysia
366	222-1465-3 51	TM5RJ3-88(51)	Malaysia	Indonesia	May-2016	Malaysia
367	222-1465-3 52	TM5RJ3-88(52)	Malaysia	Indonesia	May-2016	Malaysia
368	222-5085-4 50	TM5RJ3X-64(50)	Malaysia	Indonesia	May-2016	Malaysia
369	222-5087-0 50	TM5RJ3X-88(50)	Malaysia	Indonesia	May-2016	Malaysia

**Acknowledgment**

(Customer -> Hirose Electric business representative)

**Notice of the Addition of a Production Location for Products Manufactured  
at our Malaysia Factory and Request for Your Acknowledgement**

We acknowledge the aforementioned matter.

●Customer's name: \_\_\_\_\_

●Acknowledgment stamp (or signature): \_\_\_\_\_

HIROSE ELECTRIC CO., LTD.

-----  
(Cut on this line)

**Document Receipt**

(Customer -> Hirose Electric business representative)

**Notice of the Addition of a Production Location for Products Manufactured  
at our Malaysia Factory and Request for Your Acknowledgement**

We acknowledge the aforementioned matter.

●Customer's name: \_\_\_\_\_

●Acknowledgment stamp (or signature): \_\_\_\_\_

HIROSE ELECTRIC CO., LTD.