

# Engineering Change Notice

Part No. <u>1043P</u>	ECN No. <u>17-005</u>
Part Name <u>BATTERY HOLDER</u>	Date <u>1.04.17</u>
Rev. <u>A</u>	ECR No. <u>—</u>

Description of Change:  Drawing Attached

THE RECOMMENDED MOUNTING HOLE WAS INCORRECT.  
INSTALLATION OF THE HOLDER INTO THE BOARD WAS DIFFICULT.  
CHANGE CENTER CONTACT MOUNTING LEGS FROM 2.822 TO 2.845  
INCREASE MOUNTING HOLE DIA. FROM .135 TO .140

Solution:  Tooling Change Required

REVISE C+M DWG

Disposition of Parts:

U.A.I.

Signed \_\_\_\_\_ Date 1.04.17

Required Distribution:

Engineering     Quality Control     Purchasing     Manufacturing/Supplier

Chief Engineer: \_\_\_\_\_ Remarks: \_\_\_\_\_

Signed \_\_\_\_\_ Date 1.04.17

Document Control: \_\_\_\_\_ Rev. B

Change Incorporated    Signed \_\_\_\_\_ Date 1.04.17