

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description
SBU	PG	PUG	Type			
01	001	023	0000000351	See list below	Circuit Protection	UMF 250

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected	
3405.0176.11	3405.0176.24





*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of Approval
- Change of Label
- Change of Marking

3 Detailed description of change

The 10A version got newly approved by VDE on the IEC 60127-7. Since this part 7 doesn't allow to use some reserved characters, we change the product marking and labels accordingly.

Old product appearance	New product appearance
	
Old label	New label
	

4 Reason of change

The 10A version was originally not approved by VDE. To meet new customer demand, we approved this fuse according to IEC 60127-7.

5 Release date

The change is available from ww 25/2020 (production date code 2025 or higher).

6 Impact of change and recommended action

Form	No	No action recommended
Fit	No	No action recommended
Function	No	No action recommended
Manufacturing	No	No action recommended

Product Change Notification					UMF 250 10A marking		
owner	creation date	release date	released by	change order no	rev	page	D10-046-613
schmidre	22.06.2020	24.06.2020	haeckima	2020169	A	1 of 2	

Label	Yes	No action recommended since the fuse itself hasn't changed
Packaging	No	No action recommended

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					UMF 250 10A marking		
owner	creation date	release date	released by	change order no	rev	page	D10-046-613
schmidre	22.06.2020	24.06.2020	haeckima	2020169	A	2 of 2	