

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	013	0000002297	See list below	Appliance outlet	4797	

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)



List of part numbers affected				
4797.0000	4797.0010	4797.0012	4797.0012.02	4797.0015
4797.0020	4797.0025	4797.0030	4797.0100	4797.0110
4797.0112	4797.0115	4797.0120	4797.0125	4797.0130
4797.3000	4797.3010	4797.3012	4797.3015	4797.3020
4797.3025	4797.3030	4797.3100	4797.3110	4797.3112
4797.3115	4797.3120	4797.3125	4797.3130	

**2 Type of change**

Change of markings

**3 Detailed description of change**

The part number is no longer printed on the product.

Old product appearance	New product appearance
	

**4 Reason of change**

Marking of the material number is no longer required by the Chinese customs authorities.

**5 Release date**

The change will be rolled-out starting ww 44/2016 and lasts approx. 9 months, depending on the variant.

**6 Impact of change and recommended action**

Form	Yes	Change of lettering
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">Data Sheet 4797</a>	

Product Change Notification					PCN 4797		
owner	creation date	release date	released by	change order no	rev	page	D10-009-936
hotzar	2017-01-19	2017-01-19	hotzar	2011292	B	1 of 1	