

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	010	0000000512	0031.3551	Circuit protection	FAB Fuseholder 5x20	n/a
				0031.3558		FAB Fuseholder 5x20	n/a
				0031.3553		FAB Fuseholder w/o fuse carrier	n/a
				0031.3557		FAB Fuseholder w/o fuse carrier	n/a



*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of material markings

3 Detailed description of change

Enlarged product name and approval marks on the product. Ratings are now visible on the product label.

Old product appearance	New product appearance
	

4 Reason of change

- Improved readability of the product markings.

5 Release date

The change will be rolled-out starting ww 01/2021 (Date code 2101 or higher on label).

6 Impact of change and recommended action

Form	Yes	Change of markings
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					Inscription change FAB		
owner	creation date	release date	released by	change order no	rev	page	D10-049-007
dislercy	13.10.2020	15.10.2020	bucherfa	2020792	A	1 of 1	