1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Туре				
01 0	002	003	0000000523	0031.1706 0031.1751 0031.1754 0031.1759 0031.8824	Circuit protection	FEU 5x20	n/a
			000000680	0031.1757		FEU Medical	n/a

^{*}SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)


2 Type of change

• Change of country of origin of various fuse holders

3 Detailed description of change

The country of origin of the fuse holders FEU equipped with 5x20mm fuse carrier has changed from Switzerland to Czech Republic.

Label adjustment:



4 Reason of change

• Reorganization of production process.

5 Release date

The change will be rolled-out starting ww 01/2017 (date code 1701 or higher on label).

6 Impact of change and recommended action

Form No No change in form

Fit No No change for dimension

Function No No change in function

Production Site No No change of the production site

Label Yes Modified label for change of the country of origin

Packaging No No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet	for Fuse carrier type FEU
Data sheet	for Fuse holder type FEU (Medical)
Data sheet	for Fuse holder type FEU